## **SURVEY &** REMONUMENTATION

MAR 1 3 1998

SECTION

## 1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

For corners in: NORTH BRANCH TWP.			97 NOV 12 PM 2: 55				
LAPEER (County)	Located In:	Corner Code#		Molisea	De V	aush	
Public Land Survey	T <u>09N</u> R <u>11E</u> T R T R	A-1	Melissa. Da Vaugh  REGISTER OF PEEOS LAPEER COME CHIMPAN				
Property Controlling in Section S     Miscellaneous Property in Sec. S	T R T R		Register of De	eds Stamp	& File	Numbe	er
4. Lot No, Rec 5. Private Claims	orded Plat		1 A B C 2	D E F	G H	J J	K L I
I, JONATHAN M. FIELD , in a field survey on JUNE 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			5	8 9	10	11	
			1 1	20 21	22	23	24
expressed below.		and range, may be recorded	11 31	29 28 32 33	27 34	26 35	25 36
38.2' 24" MAPLE 1975 SMITH SURVEYING:	SET POST; MAPLE 16 S26 #14096; SURVEY; L.001,I SMITH, P.S.#21582; SUR AVLIN, P.S.#23510; SUR\ !N 20" MAPLE, SOUTH 23	6W 52LKS., BEECH 12 N63E 3 PG.043; 1/2" IRON; N60W 34.6 RVEY; L.003,PG.432-433; FND.	' 24" MAPLE, S				45W

1987 HENDERSON-BATE; ELRICH, P.S.#18986; SURVEY; L.007,PG.718; FND. 1/2" IRON; SAME WITS AS 1978 SURVEY 1988 GRAVLIN, P.S.#23510; SURVEY; L.007,PG.885; FND. 1/2" IRON; SAME WITS AS 1978 SURVEY ABOVE 1993 FIELD, P.S.#37276; 1993 REMON LCRC FOR M-13 T10N-R10E; FND. 1/2" ROD

M-1 TO L-1 2642.52' GRAVLIN '88 & '78; SMITH '75

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1997 ROWE; FIELD, PS#37276; FND. 1/2" W/ STANDARD REMON CAP RECOVERED ALL 1993 REMON WITS CITED ABOVE

NOTE: THIS CORNER IS COMMON WITH M-1 T9N-R10E, M-13 T10N-R10E, AND A-13 T10N-R11E

Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1/2" ROD W/ STANDARD REMON CAP

S63°E, 77.94' NAIL W/ REMON TAG IN NE FACE CUT-OFF T.POLE S48°E, 42.61' NAIL W/ REMON TAG IN SW FACE 26" MAPLE

S02°W, 23.87' NAIL W/ REMON TAG IN W. FACE 14" ASH N06°W, 25.99' NAIL W/ REMON TAG IN E. FACE 10" ASH

N47°W, 35.49' NAIL W/ REMON TAG IN SW FACE 30" MAPLE

Signed by r's Michigan License No.

PEER BROUN/-// APPROVED LAND CORNER

ER COUNTY

RAY DAY S P.S. CO. SURVEYOR DATE

345 CF 1990

JONATHAN M. FIELD PROFESSIONAL SURVEYOR 37276 DINO SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993

LIDER 0005 PAGE 0453