

MAR 23 2000

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in					RECEIVED FOR RECORD							
Lapeer (County)	Located in: North Branch Twp.	Corner Code #	99 DEC 14 AM 9: 15									
1. Public Land Survey	T 9N R 11E T R	A-7	Melissa De Vaugh REGISTER OF DEEDS									
2. Property Controlling S	T R T R T R		Register of Deeds Stamp & File Number								Ser	
in Section S T R 3. Miscellaneous S T R Property in Sec. S T R												
4. Lot No, Recorded Plat A B C D E F G H I J K L M												
		•		1 2 3	6	5	4	3	2	1		
I, Earl E. Gravlin, in a field survey on July 23 19 99, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						8 17	9 16	10	11	12		
						20	21	22	23	24		
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 13					19 30	29	28	27	26	25		
					31	32	33	34	35	36		
GLO: 1834 Burnham, in range line 15 links South set post, b ash 20 N32E 17, elm 12 S81E 13. County Surveyor: 1905 Sickelsteel, set stone 19x9x9 with small stone, found orige lm bearing S81E 13, elm 24 S4W 16 1/2; 1907 Sickelsteel, stake, burr oak 40 N27E 70, elm 28 S42W 44. 1988 Gravlin L7 P973, found iron shaft, S30W 40.03' 12" box elder, N45E 46.78' 10" box elder, N35W 58.30' 6" elm, East 27.64' top of fence post, cor common to se cor see 13 T9N-R10E, Deerfield Township. 1988 Gravlin L4 P163 Act 74, S30W 40.03' 12" box elder, N45E 46.78' 10" box elder, N35W 58.30' 6" elm, East 27.64' top of fence post. 1989 Elrich L8 P597, S30W 40.03' spike 16" box elder, N45E 46.78' spike 10" box elder, S45E 34.00' spike fence cor post, South 6.40' West leg of sign, found 1/2" x 12" bolt. 1991 Gravlin L4 P372, same as L4 P164. 1992 Gravlin L9 P987, same as L8 P597. 1994 Field L5 P176, removed bolt set 1/2" rod w/standard brass cap, South 6.42' W. edge of W. sign post leg, S33W 40.03' find nail w/flag in SE face 18" basswood, N44E 46.74' find nail w/flag in S face 16" box elder, East 27.69' set nail w/remontag is S face fe post, S41E 34.04' find nail w/flag in NE face fe post. 1997 Kay job #97-133, find steel stake, S45E 22.83' spike 10" oak, N40E 30.29' spike 8" maple, West 33.14' capped iron #18986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner by the standard brass cap on 1/2" iron on centerline of road. Witnessess match M-7 T9N-R10E. Accepted rod as a perpetuation of original corner. M-7 T9N-R10E accepted by peer group as common to A-7. A 7 to A 21-2640 by peer group as common to A-7.												
A-6 to A-7 2634.85'							111	PHILL	101223 11111111	NACIN	19.	
C. Description of monument of A-7 section corner common to a Found standard brass cap on 1/2 South 6.42' West edge of West: S33W 40.03' found nail w/flag in N44E 46.74' found nail w/remon S41E 34.04' found nail w/flag in Signed by	or sign post leg in SE face 18" basswood in S face 16" box elder tag in S face fence post		etuate locati	ing th	ne po			If y	ED L		UP CORNE 270 28TY SURVEY	
Surveyor's Michigan License No.	23510	Date	FORM	APPROV	ED BY III	ICHGAN	STATE	DOARD O	F LAND \$	URVEYOR	S. JAN. 28, 1971	