BUNVEY & REMONUMENTATION

APR 2 9 1996

REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

95 SEP -7 PH 3: 08

LIBER NO. 5 INGE NO. 5 Melisur Da Vaush REGISTER OF DEEDS LAPEER OF THE YESTERGAN

For corners in LAPEER ocated in: Corner Code ## North Branch 9N1 -5 11E R ___ Public Land Survey Τ _ R _ Т R. Т R Property Controlling Т _ R . in Section S T_ Miscellaneous S T R Property in Sec. S Т_ R

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat
5.	Private Claims

Earl E. Gravlin July 19th in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

F 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

History: Burnham 1834 Post Sugar 12 N26E 25 Beech 8 S61W 13 L-5 to M-5 39.72 County Surveyor Bates 1867 Stone, Elm 3 S26.5W 41.5 Pine 34 S83.5E 18 Act 74: L4 P 372 Gravlin Fnd Mon Box S20W 34.0 Nail TP N30W 54.0 Nail 10" Elder N45E 55.15 Face Road Sign L4 P 344 Davis Fnd 1/2" Iron in Mon Box S10W 34.33 Face Utility Box N30W 53.64 Nail 10" Elder N45E 55.15 Face Road Sign S 33.00 Cap Iron 14096 Recorded Surveys L6 P742 Gravlin same as Act 74 L4 P 372, L9 P 96-97 Gravlin same as Act 74 L4 P 372, L 10 P 256 Gravlin same as Act 74 L 4 P 372, Unrecorded surveys Davis 5-20-90 90-38 Same as Act 74, L 4 P 344, Kay 78-211 10/17/78 Same as Act 74 L 4 P 372. Road Commission, N45°W 53.44' 8" Tree, N40°E 38.10' Iron, South 33.18' Iron. Drain Commission Nothing.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site Conditions: Found Boat Spike in Mon Box, Rolling Farmland, Asphalt Road East and West, Old fence row to South Gravel Road to North L-5 to M-5 2623.27 L-5 to K-5 2622.00

> PEER GROUP APPROVED LAND CORNER PA 345 OF 1990 APEER COUNTY

AVIS P.S. CO. SURVEYOR

7-13-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

July 19th, 1995

FOUND BOAT SPIKE IN MON BOX, REPLACED WITH 1/2" RE-ROD AND BRASS CAP

SO5°E 45.63' NAIL & TAG W SIDE 10" TWIN ELM

SOUTH 33.0' KAY ENGINEERING IRON

S50°W 47.22' NOTCH S END 24" CMP

N35°E 67.68' FACE BURIED CABLE SIGN

Date Signed by _ 225 Surveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971