SURVEY & REMONUMENTATION

OCT 2 9 1996

REMONUMENTATION

CON	111	33	
-----	-----	----	--

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FO	BECORI ث
-------------	----------

For	corners	in
	COLLICIO	.,,

LAPEER Located In: Corner Code ## (County) A-1 9N 12E 1. Public Land Survey __ R _ _ R Т Τ. R. 2. Property Controlling Τ_ _ R .. in Section

___ R __

_ T .__

_ T _

96 SEP 30 PH 3: 10

Helica I. Rangh

Register of Deeds Stamp & File Number

___ , Recorded Plat __

Private Claims _

Miscellaneous

Property in Sec.

AUGUST 96 EARL E. GRAVLIN , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

H

A. Description of original monument and accessories and/or subsequent restoration:

History: Corner set by Joseph Wampler, 1821. Reset or found by Parke in 1834. Witnesses Elm 16 S16°W .13 B Ash 16 N5°W .16 Set post County Surveyors Record: Book 2, page 62, Bates 1868, no witnesses. A-1 to A-2 46.11 CH 3043.26'. Act 74 None. GLO M-1 to M-2 T9N-R11E-47.97 CH 3166.02'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site conditions: flat farmland abandoned road east & west ditch to south, fence to north. In October, 1993, Remon M-13, T10N-R11E, found 1/2" iron lying on ditchbank, apparently disturbed by recent ditch cleaning. Re-set corner on extension of North South fences in center of old East West road bed. MEASUREMENT A-1 TO M-12 SEC 36 T10N-R11E 2632.91 AND A-1 TO M-2 T9N-R11E - 3181.24 A-1 TO A-12 T10N-R11E 3054.59

Corner common to 3 adjoining townships.

Description of monument for corner and accessories established to perpetuate locating the position of the 295 error.

*

Prof. Surveyor

A-1 NORTHWEST CORNER, SECTION 6, T9N-R12E

Found 1/2" iron with brass cap on extension of North South fences in center of BIGHOUP

East West road bed. East West road bed. PA 345 OF 1990

N20°W 22.18' NAIL & TAG 6" ASH

\$55°W 41.45' NAIL & TAG 12" ELM

S05°E 38.26' NAIL & TAG 20" ASH

NO5°W 68.01' NAIL & TAG 12" ASH

Surveyor's Michigan License No. __

RAY DAVISPES, CO. SURVEYO

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

EEB COUNTY