REMONUMENTATION

seci a amin	-		الجي دويون ساه د
MOTORE		R RECORDATION CERTIFICATION OF A CONTROL OF	KEREIAED LOV VECCOUR
For corners in			98 NOV 25 AM 9: 28
LAPEER	Located In:	Corner Code ##	20 MOA 52 MIL 2, 50
(County)	•		-m ->
	Burnside Sou		Melissi Da Vaugh
1. Public Land Survey	T 9N R 12E	A-10	and an arrac
	T R		REGISTER OF DEEDS LAPEER COUNTY, MICHIGAN
	T R		CALETY 200
	T´ R		
	T R ¹		D. Committee of the control of the c
in Section S	- <u>·</u> -T- <u>· · · ·</u> R'- <u>· · · ·</u>	190	
3. Miscellaneous S	T R	\	egister of Deeds Stamp & File Number
Property in Sec. S	T R		
1. Lot No, Recor	ded Plat		A'B'C DEEGHIIJEK'LN
5. Private Claims			A B C D E E G H. I JEK L N
-	· · · · · · · · · · · · · · · · · · ·		2 - 6 - 1 - 5 - 4 - 3 - 1 - 2 - 1 -
			3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
			4
Earl E. Gravlin in	a field surrou on July 1	L5 10 98	5
		of 1970, the corner points mentioned	
		d rules therefore as required in the	6 18 17 16 15 14 13
current manual of survey instruction	ns of the United States Depart	ment of the Interior, Bureau of Land	7
-		r points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
		f Land Surveyors or by a Decree of a	9
⊃ourt of Law; established, re-est ∍xpressed below:	ablished, monumented, re-n	nonumented, recovered, found as	10 20 20 27 26 25
·	**		20 20 20 20 20 20
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11 + + + + + + + + + + + + + + + + + +
on this certificate.		-	12 -31 -32 -33 -34 -35 -36
			13
Burnham. Corner not s 28, Pine Stump 24 N51W Unrecorded survey, Gra occupation to East, S4 side 10" Box Elder N60	te run by Joseph Wantet. County Surveyor 60. A-10 to A-11 wlin, Date 6-26-199.0W 46.45 nail & tag E 18.59 nail & tag 43.29 to E 1/4 cor	mpler. 1834 Subdivision or Record: Book 2 1867 st 39.98 (2638.68), A-10 to 88, Job No 980114, Set Ir y N side 6" Box Elder, N4 W side 10" Box Elder, S1 Sec 25 T9N-R11E. Road C	ake Pine Stump 34, S50W A-9 same. Act 74 none. on, on range line at good OW 35.16 nail & tag E OE 97.34 nail & tag W
3. Description of corner evider	nce found and/or method a	applied in restoring or reestablishin	g corner:
Site Conditions: Rolli gravel North-South, fe 2642.46, A-10 to A-9 2	nce row to East, A-	·	1321 ±, A-10 to A-11
			PEER GROUP
		APPRO	OVED LAND CORNER
		<u>\</u>	PA 345 OF 1990
		1	REER COUNTY
		RAY DAX	IS P.S. CO. SURVEYOR
		DATE	4- <i>17-9</i> 8

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NOVEMBER 9, 1998 FOUND 1/2" RE-ROD IN PLACE, SET BRASS CAP S40°W 46.45' NAIL & TAG NORTH SIDE 6" BOX ELDER N40°W 35.16' NAIL & TAG EAST SIDE 10" BOX ELDER N60°E 18.59' NAIL & TAG WEST SIDE 10" BOX ELDER S10°E 97.34' NAIL & TAG WEST SIDE 16" CEDAR SOUTH 43.29' M-10

STATE OF MICHORAL EARLE. GRAVLIN 23510 & 23510

DATE

Surveyor's Michigan License No. 235/0

1880008 Held 0.88

MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

continued White and She con