BUHVEY & REMONUMENTATION

APR 2 9 1996

For corners in

on this certificate.

REMONUMENTATION

COMMISSION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

• 	95 SEP -7 PH 3: 04
	LIBER NO. 5 PAGE NO. 270
	Melissa Da Vaugh
	REGISTER OF DEEDS LAPEER COUNTY, MICHIGAN
	LAPEER COUNTY, MICHIGAN

RECEIVED FOR RECORD

LAPEER		Located In:	Corner Code ##
(County)		Burnside South	Comer Code ++
		9N 12E	M-3
1.	Public Land Survey	T R	
		T R	
		T R	
		T R	
2.	Property Controlling	S T R	-
	in Section	S T R	· · · · · · · · · · · · · · · · · · ·
3.	Miscellaneous	S T R	
	Property in Sec.	\$ T R	

Register of Deeds Stamp & File Number

4. Lot No, Recorded Pla	t		^ _	C'.D E	1.	ار ان افسان		
5. Private Claims					7 G 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- T	┺
			26	┤ ┈┊┈┼┈	- 4 3	1	!——	· † .
			3	-	┥┩┥			+
Earl E. Gravlin	July 19th	95	4 7	├— 8— -	- 9	0 <u>-</u> ¹	1—	·12
	urvey on		5	1-1-1-	4-4-4			1
do hereby certify that under requirements of F in lines 1 and 2 above were in conformance current manual of survey instructions of the	6 18-	17	 -16	51	4—	13		
Management or by a decree of a Court of Law above were in conformance with the rules of	8 - 19-	20	21 2	2 2	3 —	24		
Court of Law; established, re-established expressed below:	1030	29	28 2	72	6	25		
NOTE: Not more than 4 corners, all in	11					Ĺ		

A. Description of original monument and accessories and/or subsequent restoration:

History: Parke 1834 Set Post Beech 9 S83W 16 Do 24 N41W 38 Common to A-3, County Surveyor Bates 1878 Stone 34" long No witness M-3 to M-4 40.15, Act 74 None, Recorded Surveys Kay, L1 P 423 Fnd 3/4" Re-Rod N45E 50.9 Nail 28" Maple, N80W 50.08 RR Sign, S15W 40.55 RR Sign,, Unrecorded Surveys Brown 12/21/89 Job# 89-124 Fnd 3/4" bar N40E 50.80 Nail 24" Maple, S20W 40.60 RR Crossing Sign, S45E 48.6 Nail PP, Bailey Sec 7, T9N-R13E Sanilac County, 3/20/95, Job # B95-164, Fnd 5/8" Iron, N45E 51.5 PK 24" Maple, N20E 89.10 PK 30" Maple, S45E 48.58 Nail PP, N75W 50.07 SE Cor RR Sign. Road Commission, N75°W 94.10' 14" Maple, N55°E 52.33' Thornapple, S 44.05' Spike. Drain Commission Nothing.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site Conditions: Found 5/8" Rod in Gravel Intersection, Level Farmland, Gravel Road North, Gravel Road East, Asphalt Road South, Gravel Road West, M-3 to M-4 2633.33, M-3 to M-2 2643.57.

PEER GROUP
APPROVED LAND CORNER
PA 345 OF 1990
LARBER COUNTY

RAY DAVIS P.S. CO. SURVEYOR DATE 7-13-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

July 19th, 1995
FOUND 5/8" ROD, REPLACED WITH 1/2" RE-ROD AND BRASS CAP
N20°E 89.04' NAIL & TAG W SIDE 30" MAPLE
N38°E 51.44' NAIL & TAG E SIDE 24" MAPLE
S47°E 48.43' NAIL & TAG S SIDE POWER POLE
N73°W 50.11' FACE RR CROSSING SIGN

Signed by Surveyor's Michigan License No. 23570

8-17-95

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983

Date