## SURVEY & REMONUMENTATION

APR 2 8 1995

## COMMISSION

## REMONUMENTATION

RECEIVED FOR RECORD

For corners in		Filing Requirement of Act 74, Mich. P.A. 1970				94 <b>i</b> 32r i										
_	Lapeer .Countys	<del></del>	Located In:	Corner Code ##			1	ita To	iste Iste	. D 1 51	24. 	ueis C	< :		_	
1.	Public Land Survey		T <u>9N</u> R <u>12</u> E T R T R T R	M-7			LAÍ		Ti i.			1,7	CA	4		
2.	Property Controlling		T R													
	in Section	S	T R													
3.	Miscellaneous	S	T R		D:-						_			_		
	Property in Sec.	s	T R		Regis	ter	or De	ea.	S 51	amı	р & ———	FILE	· N	 amp	.er	
4.	Lot No	Recorded	i Plat													
5.	Private Claims		1,			^	B (	;	D E	F	G	H	1	<del>) )</del>	<u> </u>	

I. Earl E.Gravlin in a field survey on September 19 94. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Wampler, 1822, page 631, Set Post, Ash 9 N40W 8, Birch 8 S21W 11, BURT 1834 INT, at post, Birch 10 N 42E 27, Birch 8 S 57 1/2 E 51. ACT 132 FORMS\_Kay L 3, P 347, 1975, FND 3/4" Bar EAST 30.41' NAIL IN PP, S 45°W 61.38'NAIL IN TP, S 35°E 71.16 NAIL BRACE POLE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Flat farmland, gravel road, centerline road to West. Found 3/4" Bar, M-7 to M-8 2619.04' M-7 to M-6 2628.46'

PEER GROUP
APPROVED LAND CORVER
PA 345 OF 1990
LYEER COUNTY
RAY DAY OF P.S. CO. BURYZY OR
DATE

| 1/2 | 1/3 - 7/4

Description of monument for corner and accessories established to pernetuate incating the nosition of the corner.

November 7, 1994
Found 3/4" Bar, Replaced with 1/2" Iron with brass cap N 43°W 79.91' NAIL IN N/S POWER POLE, S 58°W 61.39' NAIL IN S/S POWER POLE, S 26°E 71.02' NAIL IN W/S BRACE POLE, EAST 30.33'\_NAIL IN S/S POWER POLE



Signed by Date //-17

Surveyor's Michigan License No 1, 235/6

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 28 197