SURVEY & REMONUMENTATION

COMMISSION

1993

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

For corners in

5. Private Claims __

expressed below:

Filing Requirement of Act 74, Mich. P.A. 1970

MUNITARE	210 24. 625 1546
93 DEC 22	M1 3: 64
LIBER SOL	33 <u>33</u>
Miles.	
LATITATION OF THE	1. Canta

DEPENDED FOR RECORD

LAPEER Located In: Corner Code ## (County) T 9N R 12E M - 101. Public Land Survey T _____ R ____ __ R _ ____ Ř _ 2. Property Controlling T _____ R ___ in Section __ T ____ R __ 3. Miscellaneous __ T .____ R __ Property in Sec.

___ , Recorded Plat _____

Register of Deeds Stamp & File Number

C.DEFG

Ĥ

8

12 13

I, <u>Earl E. Gravlin</u>, in a field survey on <u>October</u>, 19 <u>93</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-10. East quarter corner Section 25. History: East and South town lines run by Joseph Wampler, 1821. Pages 630 and 631. Subdivision of township run by Hiram Burnham, second quarter, 1834. page 638-640. Witnesses Elm 9 N25°W 20 Sugar 14 S53°W .28 SET POST. County Surveyors Record: Nothing. Surveys(30-9-13 Kay 1/14/86 Kay 3/1/83

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

Site conditions: Flat farmland Cade Road(gravel) Fenceline stonerow and treeline to west. Found 1/2" iron 10.45' North(W 1/4 cor sec 30-9-13)
MEASUREMENT M-10 TO M-11 2637.59' M-10 TO M-9 2678.28' M-10 TO FENCE TO WEST 1335'NORTH

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

October 19, 1993

Surveyor's Michigan License No. _

Found 1/2" iron 10.45' North(W 1/4 cor sec 30-9-13)

Set 1/2" iron with brass cap, on line at occupation fence to west.

N89°W 37.33' NAIL & TAG N SIDE 4" MAPLE

N38°W 45.97' NAIL & TAG N SIDE 24" HICKORY

N24°W 150.65' NAIL & TAG E SIDE POWER POLE

S21°E 73.55' NAIL & TAG W SIDE 14" ASH

EARL E. GRAVLIN
Prof. Surveyor
No.
23510

AOFESSIONAL
MINISTRACE
M

Signed by SSS

Date 12/02/93

MOVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

LIBER 005 FASE 33