1993

Property in Sec.

Private Claims \_\_

4. Lot No.

expressed below:

## REMONUMENTATION

## RECEIVED FOR RECORD

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| 93 DEC 22 | PH 3: 05                 |
|-----------|--------------------------|
| JEEF N. 5 | 34                       |
| Mensse    | 11 655                   |
| FFCC:FT   | 17 (1200년)<br>19 (1202년) |

For corners in LAPEER Located In: Corner Code ## T 9N R 12E <u>M⊶1</u>1 1. Public Land Survey \_\_ R \_ \_\_ R. \_\_ R. **Property Controlling** \_\_ R \_ in Section \_\_ T \_\_ \_ R S Miscellaneous S \_ T .\_\_\_\_ R \_

Т

\_ , Recorded Plat \_

R

Register of Deeds Stamp & File Number

Earl E. Gravlin , in a field survey on October do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land  $\textbf{Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5$ above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Ε 'F D 8 C, G н 10 11 12

Description of original monument and accessories and/or subsequent restoration:

M-11. Northeast corner Section 36 History: East and South town lines run by Joseph Wampler, 1821. Pages 630 and 631. Subdivision of township run by Hiram Burnham, second quarter, 1834. page 638-640. Witnesses Beech 9 N66.5°W 24 Do 12 S19.5°W 29. County Surveyors Record: Book 2, page 96, Southwest quarter only. Recorded survey L006 P 155 Kay. Unrecorded survey Kay 1/14/86 (30-9-13)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site conditions: Flat farmland intersection Cade Road(gravel) and Willis Road(gravel). Fd 1/2" iron in place. Appears to be common with NW corner 31-9-13.

MEASUREMENT M-11 TO M-12 2640.45 M-11 TO M-10 2637.59'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

October 19, 1993

Fd 1/2" iron in place set brass cap. S61  $^\circ$ E 50.53' NAIL & TAG N SIDE FENCE POST

S48°W 75.74' NAIL & TAG N SIDE POWER POLE

N63°W 62.49' NAIL & TAG NE SIDE POWER POLE

N78°E 141.50' NAIL & TAG S SIDE POWER POLE

OF MICA GRAVLIN rof. Surveyor 23510 POFESSIONA

Signed by

ROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975