SUHVEY & REMONUMENTATION

APR 2 9 1996

RECEIVED FOR RECORD

OFFICE IN AM OLOG

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 1995 REMONUMENTATION PROGRAM

ل ر	UEU	1.0	HIT	٦,	UU
LIBER	NO	<u> </u>	20.02	NJ.	320
	Helis		1.42	رک ات	<u> </u>
	REGIS	TED I	רבי רב	<i>O</i> ∵tns	
	110010				

For corners in RICH TWP.			•		Melis	⊃	4226		-
LAPEER (County)	Located In:	Corner Code#			REGIS	TER CF,	กรรักร		
Public Land Survey	T_10N R_10E TR TR	M-8				-			
2. Property Controlling S	T R T R T R		Registe	r of De	eds S	Stamp 8	& File I	Numbe	er
4. Lot No, Recorded Plat 5. Private Claims					D D	E F (э н :	JΚ	L M
- Tivato Siamo				6	5	4	3	2	1
I, JONATHAN M. FIELD	, in a field survey on _	MARCH 19 95	4	7	8	9	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					17	16	15	14	13
					20	21	22	23	24
					29	28	27	26	25
					32	33	34	35	36
			13						

Description of original monument and accessories and/or subsequent restoration:

1833 GLO; PARKE, D.S.; SET POST; SUGAR 12 S26 1/2W 30 1/2LKS., BEECH 10 N7W 20LKS.

1986 GRAVLIN, P.S.#23510; SURVEY L.7, PG.446; SET 1/2" IRON; EAST 17.86' 8" ASH, S20E 21.95" 8" HICKORY, N40E 10.16' 6" ASH

1989 GRAVLIN, P.S.#23510; LCRC L.4, PG.259; SET 1/2" IRON; SAME WITS AS 1986 SURVEY ABOVE

1995 GRAVLIN, P.S.#23510; SURVEY L.10, PG.847; FND 1/2" IRON; S20E 21.95' 8" HICKORY, N40E 10.16' 6" ASH, N40E 3.04' 6" ASH, N85W 22.6' 8" ASH

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995 ROWE ENG.; FIELD, P.S.#37276; FND 1/2" ROD AT N. FACE OF FALLEN 12" FENCE CORNER POST ALSO FND 4 WITS GIVEN BY GRAVLIN IN 1986 INDICATING THAT FND IRON IS IN SAME POSITION PEER GROUP

G.L.O. NOTES FOR T9N-R11E IMPLY THAT THIS CORNER IS COMMON WITH AND CITED SORNER

M-8 TO M-9 2657.08' (GRAVLIN 1995) M-8 TO M-7 2647.43' (GRAVLIN 1986)

CO. SURVEYOR DATE

45 05 1390

ACCEPTED FND 1/2" ROD AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION

Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET STANDARD BRASS CAP ON FND 1/2" ROD M-8

3.11' SET NAIL W/REMON TAG BELOW FND NAIL W/FLAG. IN SE FACE 6" ASH N40°E.

10.20' SET NAIL W/REMON TAG BELOW FND NAIL W/FLAG. IN NW FACE 6" ASH N40°E,

17.76: SET NAIL W/REMON TAG IN TOP OF 10" ASH STUMP S80°E.

S20°E, 22.04' SET NAIL W/REMON TAG BELOW FND NAIL W/FLAG. IN E. FACE 10" OAK

22.64' SET NAIL W/REMON TAG BELOW FND NAIL W/FLAG. IN S. FACE 8" ASE

Signed by Date Michigan License No. 37276

JONATHAN M. FIELD LAND

ALLETED FOR WORD PROCESSIN