1993

COMMISSION

5. Private Claims \_\_\_

## REMONUMENTATION

## 'n

<b>*</b> ** ***	LAND CORNER RECORDATION CERTIFICA	
	Filing Requirement of Act 74, Mich. P.A. 197	
For corners in		

93 DEC 22	P# 3: 02
LIBER W. 5	31
1/2/20	14.5
# # 450,0 \$ # 1 <b>A</b> \$ # \$ #	i diak

RECEIVED FOR RECORD

LAPEER Located In: Corner Code ## T 10N R 12E 1. Public Land Survey T \_\_\_\_ R \_\_\_\_ T \_\_\_\_ R \_ \_\_ R . \_ T \_\_\_\_\_ R \_\_ 2. Property Controlling \_\_ T \_\_\_\_ R \_\_ S in Section \_ T .\_\_\_\_ R \_\_ 3. Miscellaneous \_ R \_ Property in Sec.

\_\_\_\_, Recorded Plat \_\_\_\_\_

Register of Deeds Stamp & File Number

Earl E. Gravlin , in a field survey on _	October	, 19 _93
do hereby certify that under requirements of P.A. 74. Mic	higan P.A. of 1970, the	corner points mentioned
in lines 1 and 2 above were in conformance with regu	lations and rules there	efore as required in the
current manual of survey instructions of the United Sta	tes Department of the	Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that	t the corner points men	tioned in lines 3, 4 and 5
above were in conformance with the rules of the Michig.	an Board of Land Surv	eyors or by a Decree of a
Gourt of Law; established, re-established, monume expressed below:	nted, re-monumented	l, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

C. D.E G - H

A. Description of original monument and accessories and/or subsequent restoration:

M-12. East quarter corner Section 36. History: East town lines run by Joseph Wampler, 1821. Page 670 North west and south lines run by Hervey Parke 1833 page 667. Subdivision of township run by Hiram Burnham, 1834. page 667. Witnesses Ash 7 S2°W .25 Beech 11 N71°W .24 set post. County Surveyors Record: Nothing. Recorded surveys Nothing

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site conditions: slightly rolling farmland Cade Road(gravel) good fence to east poor occupation to west Found 1/2" iron in place Good occupation appears to be common corner. MEASUREMENT M-12 TO M-13 2624.50' M-12 TO M-11 2624.91'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

October 15, 1993 Found 1/2 " iron in place, set brass cap N85°W 18.35′ NOTCH W END CMP N80°E 22.20' NOTCH EAST END CMP EAST 54.20' NAIL & TAG S FACE POWER POLE NORTH 2624.91' M-11 SOUTH 2624.50' M-13

**GRAVLIN** Prof. Surveyor No. 23510 ROFESSIONAL MANUEL

Signed by . Surveyor's Michigan License No. 23510 12-02-93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975** REVISED JAN., 1983