## SURVEY & REMONUMENTATION

APR 2 8 1995

For corners in

expressed below:

on this certificate.

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF LEELANAU RECEIVED FOR RECORD

1994 DEC 14 PM 2: 14

Leelanau (County)	Located In:	Corner Code ##	Bachara Kirt REGISTER OF DEEDS
Public Land Survey	т <u>29N</u> R <u>12W</u> Т R	E-1	#380
	T R T R		liber 2 PAGE 77
2. Property Controllin in Section	S R		
Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No	_ , Recorded Plat		A B C D F F O H A A K A A
5. Private Claims			2 6 5 4 3 2 1 1
Steven P. Bye	, in a field survey on <b>Novem</b>	per 16, 19 94	4 7 8 9 10 11 12
in lines 1 and 2 above we current manual of survey it	er requirements of P.A. 74,Michigan P.A. or ere in conformance with regulations and instructions of the United States Departi	d rules therefore as required in ment of the Interior, Bureau of La	lhe 7 18 17 16 15 14 13
Management or by a decre	ee of a Court of Law and/or that the corner be with the rules of the Michigan Board of	r points mentioned in lines 3, 4 an	nd5 gldllllll

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Court of Law, established, re-established, monumented, re-monumented, recovered, found as

E-1: Northwest corner of Section 4 G.L.O. notes: Between Sections 4 & 5 dated December 3, 1851, "93.70 Intersect North boundary, 95 links West of post, set post corner to Sections 4 & 5".

Sugar 16 - S 28 E, 21 links Lynn 24 - S 38 W, 24 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-1: Northwest corner of Section 4 Re-established by W.B. Batzer (RLS #13026) in survey file #73108 recorded in Liber 1, Page 410 on december 14, 1973, and monumented by Mr. Batzer in November 1989 for subsequent survey file #S89176.D13.

Record witnesses: 10" Beech - N 16W, 35.92' 12" ash - N 80 E, 46.48' Power pole - S 04 E, 45.17' Section corner 30-12 - East 62.70'

**APPROVED LAND CORNER** P.A. 345 OF 1990 LEELANAU COUNTY

10

11

12

DATE 7-28-94 COUNTY REP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Northwest corner of Section 4 1/2" iron rod with cap #13026 accepted by the Leelanau County Remonumentation Peer Review Group, July 28, 1994, and replaced with a 3/4" i.d. galvanized iron pipe 3' long with a brass cap and protective monument box.

10" Beech - No.16 W, 35.92' 12" Ash - N 80 E, 46.99' Power pole - S 04 E, 45.17' Section corner 30-12 East, 62.70'

Signed by Surveyor's Michigan License No35991

STEVEN P. BYE LAND SURVEYOR

OF MICH,

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975