

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FILE # 127

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>30</u> <sup>N.</sup> <del>S.</del> , R. <u>11</u> <sup>E.</sup> <del>W.</del>	F9
2. PROPERTY CONTROLLING IN SECTION _____	T. _____, S. _____, R. _____, E. _____, W. _____	F-G 11 (M.C.)
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____, S. _____, R. _____, E. _____, W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER'S OFFICE  
LEELANAU COUNTY, MICHIGAN  
Received for record the  
28th day of February A.D.  
1980 at 9:00 A.M. and  
recorded in Liber 1 of  
Corner Records on Page 247  
*Debra Korman*  
Register of Deeds.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Alfred V. McCann, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 18, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Described in the General Land Office Independent Resurvey of 1851.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 1/4 corner between Sections 21 & 28  
F 9 - no monuments or accessories were found - corner was restored from deed description and highway ties
- Meander Corner between Sections 28 & 33  
F-G 11 - no monuments or accessories found - corner was restored from deed description ties and GLO distance from 1/4 corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- |   |   |
|---|---|
| <p>F 9<br/>set 1" pipe with aluminum cap over "T" iron<br/>S 80° E, 25.80 ft, 40" Willow<br/>N 33° W, 88.20 ft, SE corner barn<br/>S 48° W, 141.88 ft, NE corner conc. retaining wall</p> | <p>F-G 11 (Meander Corner)<br/>set 1" pipe with aluminum cap over "T" iron<br/>S 85° E, 14.02 ft, spike in power pole<br/>S 36° W, 20.75 ft, E road<br/>N 49° W, 79.41 ft, spike in top of 21" stump<br/>S 9° W, 121.23 ft, NW corner (foundation) of house</p> |
|---|---|

SIGNED BY Alfred V. McCann DATE 2/21/80

SURVEYOR'S MICHIGAN REGISTRATION NO. 13036 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_