MAY 1 6 1997

month of Colon

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Localed in Corner Code Sections Conner Code Sections Code Code	For corners in	Ar and and		Barbara Kirt	01/10/97
1. Public Land Survey		Located In:	Corner Code #	Leelanau Res of	D. D
Private Claims Nicholas M. O'Non has feld survey on Dec. 6 1996 on hereby state that under regularments of P.A. 74 Michigan P.A. of 1970, the corner ports mentioned in lines 1 and 2 above were in regular to the properties of the interior States Operation of the corner points mentioned shall be presented to the first former of Land designation of the survey in the first or properties of the land surveys or by a Decree of a Court of Land, established, in-established, monomented, recovered, found as expressed below. NOTE: Not more than 2 comments, at in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: J-9: 1/4 Corner Common to Sections 23 and 26. G.L.O. Notes: Set Post Per Orange Riadon Survey December 18, 1851. 10" Hentlock, N 11° E, 39 Links 12" Hemlock, S 46° W, 8 Links B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-9: 1/4 Corner Common to Sections 23 and 26 Found 1 1/4" Iron Bar N. End Clear Vision Post, N 36° E, 117,73' S. End Clear Vision Post, S 76° E, 161.52' Power Pole, N 2° W, 164.70' Power Pole, S 40° W, 83.19' C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. J-9: 1/4 Corner Common to Sections 23 and 26. 1.1/4 "Iron Bar accepted as the best available evidence of the position of the original corner by the Leelanau Peer Review Group on November 12, 1996. Replaced with a 3/4" 1.D. galvanized iron pipe with stamped brases cap. Telephone Box, N 36° E, 119.33' Fower Pole, S 46° W, 83.21' Fower Pole, S 46° W, 83.21' Fower Pole, S 46° W, 83.21' Fower Pole, N 01° W, 164.71' Signed by Warrand Marken December 1 (12.7 3.0 - 9.6)	1. Public Land Survey T 30N R 12W J-9 T R			04B00002 P018S Page 1 of 1	
J-9: 1/4 Corner Common to Sections 23 and 26. G.L.O. Notes: Set Post Per Orange Risdon Survey December 18, 1851. 10" Hemlock, N 11° E, 39 Links 12" Hemlock, S 46° W, 8 Links 12" Hemlock, S 46° W, 8 Links B. Description of corner evidence found and/or method applied in restoring or reestabilishing corner: J-9: 1/4 Corner Common to Sections 23 and 26 Found 1 1/4" Iron Bar N. End Clear Vision Post, N 36° E, 117.73' S. End Clear Vision Post, S 76° E, 161.52' Power Pole, N 2° W, 164.70' Power Pole, S 40° W, 83.19' C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: J-9: 1/4 Corner Common to Sections 23 and 26. 1 1/4 " Iron Bar accepted as the best available evidence of the position of the original corner by the Leelanau Peer Review Group on November 12, 1996. Replaced with a 3/4" I.D. galvanized iron pipe with stamped brass cap. Telephone Box, N 36° E, 119.33' Power Pole, S 07° W, 132.81' Power Pole, S 46° W, 83.21' Power Pole, N 01° W, 164.71' Signed by AddMath. Other	I, Nicholas M. O'No requirements of P.A. 74, Micholas Ornance with regulations United States Department of that the corner points mention Board of Land Surveyors of recovered, found as expressen NOTE: Not more than 2 of the corner points with the corner points mention and the corner points mention and the corner points mention as expressen Note:	in a field survey on figan P.A. of 1970, the condition of	on Dec. 6 1996 do hereby orner points mentioned in lines 1 and puired in the current manual of survey in different or by a decree of a Colove were in conformance with the rule art of Law; established, re-established	state that under 2 above were in structions of the int of Law and /or s of the Michigan d, monumented, 8 19 9 10 30	S F G H I J K L M 5
J-9: 1/4 Corner Common to Sections 23 and 26. G.L.O. Notes: Set Post Per Orange Risdon Survey December 18, 1851. 10" Hemlock, N 11° E, 39 Links 12" Hemlock, S 46° W, 8 Links 12" Hemlock, S 46° W, 8 Links B. Description of corner evidence found and/or method applied in restoring or reestabilishing corner: J-9: 1/4 Corner Common to Sections 23 and 26 Found 1 1/4" Iron Bar N. End Clear Vision Post, N 36° E, 117.73' S. End Clear Vision Post, S 76° E, 161.52' Power Pole, N 2° W, 164.70' Power Pole, S 40° W, 83.19' C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: J-9: 1/4 Corner Common to Sections 23 and 26. 1 1/4 " Iron Bar accepted as the best available evidence of the position of the original corner by the Leelanau Peer Review Group on November 12, 1996. Replaced with a 3/4" I.D. galvanized iron pipe with stamped brass cap. Telephone Box, N 36° E, 119.33' Power Pole, S 07° W, 132.81' Power Pole, S 46° W, 83.21' Power Pole, N 01° W, 164.71' Signed by AddMath. Other				13	<u></u>
Found 1 1/4" Iron Bar N. End Clear Vision Post, N 36° E, 117.73' S. End Clear Vision Post, S 76° E, 161.52' Power Pole, N 2° W, 164.70' Power Pole, S 40° W, 83.19' C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. J-9: 1/4 Corner Common to Sections 23 and 26. 1 1/4 " Iron Bar accepted as the best available evidence of the position of the original corner by the Leelanau Peer Review Group on November 12, 1996. Replaced with a 3/4" I.D. galvanized iron pipe with stamped brass cap. Telephone Box, N 36° E, 119.33' Power Pole, S 07° W, 132.81' Power Pole, S 46° W, 83.21' Power Pole, N 01° W, 164.71' Signed by Malulum O'Non Date 12-30-96	J-9: 1/4 Corner	Common to Sectes: Set Post F Survey Dec	cions 23 and 26. Per Orange Risdon Cember 18, 1851.		
J-9: 1/4 Corner Common to Sections 23 and 26. 1 1/4 " Iron Bar accepted as the best available evidence of the position of the original corner by the Leelanau Peer Review Group on November 12, 1996. Replaced with a 3/4" I.D. galvanized iron pipe with stamped brass cap. Telephone Box, N 36° E, 119.33' Power Pole, S 07° W, 132.81' Power Pole, S 46° W, 83.21' Power Pole, N 01° W, 164.71' Signed by Malla M. O'Non. Date 12-30-96	J-9: 1/4 Corner Found 1 1/ N. End Cle S. End Cle Power Pole	Common to Sec /4" Iron Bar Pear Vision Post Pear Vision Post Pear Vision Post Pear N 2° W, 164.	i, N 36° E, 117.73' i, S 76° E, 161.52' 70'	APPROVED P.A. 34 LEELAN	15 OF 1990 AU COUNTY L-9 6
Signed by	J-9: 1/4 Corne 1 1/4 " I corner by galvanize Telephone Power Pol	er Common to Section Bar accepted the Leelanau ded iron pipe with Box, N 36° E, le, S 07° W, 13 le, S 46° W, 83 le, N 01° W, 16	ctions 23 and 26. ed as the best available reer Review Group on 1 th stamped brass cap. 119.33' 2.81' .21'	ole evidence of the p November 12, 1996. R	osition of the original eplaced with a 3/4" I.D.
		ul .	100	Date	