## Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

## Filing Requirement of Act 74, Mich. P.A. 1970

For cor	ners in			LENAWEE COUNTY	
Lenay	vee	Located In:	Corner Code #	FILED	
1. Pub	(County)	T <u>-5-S</u> R <u>-1-E</u>	<u>J-1</u>	8 JUL 97 1:02 P.M.	
2 Dec	nadu Cantrollina - C	TR TR TR		VICTORIA J. DAMIELS REGISTER OF DEEDS	
in S 3. Mis	perty Controlling S ection S cellaneous S perty in Sec S	T R T R T R T R		Register of Deeds Stamp & File Number	_
4. Lot	No, Recorded	Plat		A B C D E F G H I J K L A	<i>A</i>
I, Gler do here in lines current Manager above w Court of	nn E. Richard by certify that under requirement 1 and 2 above were in conformonual of survey instructions ment or by a decree of a Court of vere in conformance with the ru	nts of P.A. 74, Michigan P.A. mance with regulations and of the United States Departn of Law and/or that the corner tles of the Michigan Board o	vey on May 19, 19 97, of 1970, the corner points mentioned rules therefore as required in the nent of the Interior, Bureau of Land ropints mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a nonumented, recovered, found as	7 8 -19 -20 -21 -22 -23 -24 -	
NOTE:	Not more than 4 corner on this certificate.	s, ail in the same town	and range, may be recorded		
A. D	escription of original monu	ment and accessories an	nd/or subsequent restoration:	•	
Not set on original G.L.O. survey,  1873 Burton Kent, Co. Surveyor, surveyed Section 2 "Found the NW and NE by the witness trees"  "The N 1/4 post was set by dividing the North line equally"  1956 K. L. Suydam (employed by W. E. Frazier) set 1/2" iron pipe for N 1/4 corner Section 2  1974 I found iron pipe and recorded it in L 3 P 29  1983 K. L. Suydam found iron pipe on survey recorded in L 945 P 162  Sept. 1996 I found the iron pipe 12" deep and witnessed it and found iron pipe at J-13 T4S R1E 8.73 West  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:					
May 19, 1997 Set point in base course of asphalt so Jackson Co. Rd. Comm. could set a monument box. I set 3/4" X 3' gas pipe capped G.E.R. 13040 in monument box and is on line between Jackson Co. monuments J-13 and K-13					
	T4S Ř1É				SURVEY &
C. D	escription of monument for	corner and accessories	established to perpetuate locati	ing the position of the corner:	AliG 2 5 1997
	3/4" X 3' iron pipe capp position of the original Found iron pipe South Re-Rod (on same line a Re-rod in fence north for Dbl., hd nail & re-mon to Dbl., hd nail & re-mon to Jackson Co. Harrison n	corner. 33,16 South 72.83 rom J-13 T4S R1E N 1 ag in E. P. S 40° W 16 ag in E. side 11" Elm S	10° W 80.42 55.44 South 96.82	GLENN E. RICHARD No. 13040	COMMISSION
Ratified	l by Peer Group in accorda	nce with P.A. 345 Co.	Rep. Stone & Pular	Date 6-3-97	

Surveyor's Michigan License No. 13040