

T 55, R 2 E

SEE FRAISER AT ADRIAN
good coverage in County

x	y	
1	8	T Road N 5 + W. } set S.C. 10/31/58 Found 6" dia. stone } brass head } 50' spike over pt. via Mr. Brix } on 1" I.P. Rocks } N 16° 30' E, 76.21 Horiz spike in 13" maple S 53° E 22.84 cont. 4" I.P. for road sign S 45° E 34.97 Horiz spike in NW side 8" anchor post
1	6.95	Plot mon. 33' S. of cont. 1/4 cor.
1	6	1/4 cor. fence cor found no mon. 10/31/58
1.5	6	1/4 cor. found old wood stk in str. 1320.8' E. of 1/4 cor. set S.S. 10-31-58
2	6	S.C. not recovered 10/29/58 I.P. foot of hill reported in place by Mr. Vanimer.
0	8.7	M.C. North edge Grassy L. 3/4" x 30" I.P.
0	9	1/4 COR. Sec 7, Brass S.C. on 1" I.P. in hedgerow, 3' E. of old fence line 142.2 N. of 1/4 cor sec 12, T 55, R 1 E
0	10	I.P. (bent) Recovered 3-4-57 4" below surface of gravel rd. 6' E. of ± S.S. set 14.8' E., 146.52' (2022 ch.) N. of S.C. SE. Sec 1 Sec 1.