SURVEY & REMONUMENTATION

FFB 1 6 1999

LAND CORNER RECORDATION CERTIFICATE 1 PAGE 296

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN LENAVEE COUNTY

For corners SECTION			FILED
Lenawee (County)	Located In:	Corner Code #	10 DEC 1998 9:46:05 AM
1. Public Land Survey	T <u>-5-\$</u> R <u>-2-E</u> T R T R	_A-9	VICTORIA J. DANIELS REGISTER OF DEEDS
Property Controlling S_ in Section S_ Miscellaneous S_ Property in Sec S_	T R R T R T R R T R R T R R T R		Register of Deeds Stamp & File Number
4. Lot No, Record 5. Private Claims	ded Plat		A B C D E F G H I J K L M
I, Glenn E. Richard do hereby certify that under requiring lines 1 and 2 above were in concurrent manual of survey instruction Management or by a decree of a Company were in conformance with the Court of Law; established, reexpressed below: NOTE: Not more than 4 corr	ements of P.A. 74, Michigan P.A onformance with regulations an ons of the United States Depart ourt of Law and/or that the come he rules of the Michigan Board of established, monumented, re-	nd rules therefore as required in the interior, Bureau of Laser points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	ned the find 7
on this certificate. A. Description of original mo	onument and accessories a	nd/or subsequent restoration:	13
W. Oak 26 N 53 W 1890 James Blair fo 1963 Kenneth Suyd and found the sleigh 1973 Kenneth Suyd	/ 12, Y. Oak 20 S 10 1/2 ound cast iron sleigh shoo lam dug at Blair's record h shoe, glass, pieces of c	W 47 e, dishes and glass, center of distance from the back of the china and raised with 7" X 1' I recorded it in L. 2, P. 419	post at intersection cor Sec's 19 &30 of Church door N 89 1/2 W 90 1/2 links (59.73') ne Church steps (the church no longer standing " shaft. Nail in face of 22" Walnut S 68 E 71.73

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

September 21, 1998 Set monument box in base course of new asphalt pavement over 3/4" steel rod October 14, 1998 Replaced the found 3/4" X 20" steel rod with 5/8" X 3' re-rod with Lenawee Co. re-mon cap stamped P.S. 13040 after adjusting it 0.03 East to be on line between M-9 and M-10, T5S-R1E

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod Lenawee Co. re-mon cap stamped P.S. 13040 in mon. box and is accepted as the best available evidence of the position of the original corner.

Fd. cotton gin spike in 24" Walnut S 75°E 72.42 Fd. dbl. hd. nail & disc in 14" Wainut N 65°E 78.08 Fd. dbl. hd. nail & disc in 24" Hickory N 10°W 126.51 Survey mark spike and re-mon tag in 13" Hickory S 20° W 79.16 Iron pipe capped W.E.F. 17636 N 25° W 83.23

M-9 T5S-R1E, North 76.48

ATE OF MICHIQA GLENN E. RICHARD No. 13040 STONAL SU Marin Street and Assessment

Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Lenne Kicken	_ Date_	11-3-98
Ratified by Peer Group in accordance with P.A. 345 Signed by Signed by Glenn E. Richard	ate Nov. 10, 1998		
Glenn E. Richard	7-7-		

Surveyor's Michigan License No. 13040