JA:12 7 2000

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

## Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

San Contract					
For corners in _Lenawee (County)	Located In:	Corner Code #	LIBER :	1 PAGE 344 STATE OF LENAVEE	MICHIGAN
1. Public Land Survey	T <u>-5-S</u> R <u>-2-E</u> T R	C-11		FIL	ED
2. Property Controlling S	T R R			29 SEP 1999	
in Section S_3. Miscellaneous S_	T R T R		Register of	REGISTER	J. DANIELS OF DEEDS & File Number
Property in Sec S  4. Lot No. Reco  5. Private Claims			1	CDEFG	;ні ј к L N
i. Glenn E. Richard	in a fiel	ld survey on July 19, 19	2 6 3 4 7	8 - 9 -	-10 - 11 - 12 -
do hereby certify that under requ In lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a 0	direments of P.A. 74, Michigan conformance with regulations the United States Depote that the court of Law and/or that the co	P.A. of 1970, the corner points ment and rules therefore as required in partment of the Interior, Bureau of corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decre	tioned 6 18- in the 7 Land 7 and 5 8 19-	17 6 - 20 - 21 -	15 14 13 22 23 24
Court of Law; established, re expressed below:	e-established, monumented,	re-monumented, recovered, foun	d as 9	29 28	27 26 25

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

G.L.O. 1824, Hervey Parke set post corner Sec. 29, 30, 31 & 32 Y. Oak 34 S 39 E 40 W. Oak 30 N 14 1/2 W 41 Could not find any information on this corner in any of the old survey records.

1935 Walter Frazier surveyed Slee Rd. "Set hub" S 56 W NE corner of stone porch 99.7

1967 The corner was re-established by Gillespie and Associates

1972 Werner Sommer found iron and recorded it in Liber 1, Page 679

1974 Kenneth Suydam did a survey in Section 29 and labeled the corner as "Found Iron"

1995 Steve Young found iron pipe

on this certificate.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 19, 1999 I found a 3/4" X 12" iron pipe 10" deep under base course of new asphalt pavement. Replaced it with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

NE comer of stone porch S 50° W 90.42 Fd. 60d spike in 24" Locust S 15° W 60.78 Set dbl hd nail & Lenawee County Re-mon tag in 24" Locust S 10° E 87.35



Fd. dbl hd nail & Aluminum disc E.P. N 50° E 70.72	GLENN E.
	RICHARD No. 13040
	Standard Street
$\mathcal{M}$ a $\mathcal{O}$ $\Lambda$	
Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Lenn Chicke	Date September 14, 1999
Signed by January Date Sept. 24,1999 Glenn E. Richard	
Surveyor's Michigan License No. 13040	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
	REVISED MAY 14, 1975
	REVISEO JAN., 1983
	Adapted for word processing march, 1993