JAM 2 5 2000

Harry Commence Control &

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

## Filing Requirement of Act 74, Mich. P.A. 1970

SECTION	#E		
For corners in Lenawee	Located In:	Corner Code #	LIBER 1 PAGE 346
(County)  1. Public Land Survey	T <u>-5-S</u> R <u>-2-E</u>	<u>E-11</u>	STATE OF MICHIGAN LENAWEE COUNTY FILED
Property Controlling S     in Section S     Miscellaneous S     Property in Sec	TR		29 SEP 1999 5:57:47 PM  VICTORIA J. DANIELS  Register of Deeds (1916) (1916) (1916)
I, Glenn E. Richard do hereby certify that under rec In lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a	puirements of P.A. 74, Michigan P.J conformance with regulations a clions of the United Stales Depar Court of Law and/or that the corr	urvey on <u>July 20, 19 99,</u> A. of 1970, the corner points mentioned in the trues therefore as required in the truent of the Interior, Bureau of Land her points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a	7 8 19 20 21 22 23 24
		e-monumented, recovered, found as	10 30 29 28 27 26 25
NOTE: Not more than 4 con this certificate		n and range, may be recorded	11 12 31 32 33 34 35 36 13
A. Description of original	monument and accessories a	and/or subsequent restoration:	
Could not find an		st W. Oak 18 N 53 1/2 W 59 er in any of the old survey reco	

1972 Kenneth Suydam's survey recorded in Liber 1 of Surveys on Page 278 calls for iron pipe. The notes

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1974 Werner Sommer found 1" iron pipe and recorded it in Liber 2, Page 675

July 20, 1999 Found iron pipe under base course of asphalt pavement. Replaced it with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 and set monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd 60d spike in N, face of E.P. S 45° W 47.15 Fd. nail & disc in NE face of E.P. S 45° W 47.02 Fd dbl hd nail & disc in 14" Oak S 35° E 74.26 Set dbl hd nail & re-mon tag in 22" Oak S 5° W 127.05 East edge of stop sign post N 25° W 43.29

The corner is 0.5 North of pavement centerline

don't show whether set or found.

1995 Steve Young found iron pipe

MICHORNIA OF MICHIGAN STATE OF MICANOR GLENN E. RICHARD No. 13040 STOWN SIR Chilard Date September 14, 1999

Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Sleven Le
Ratified by Peer Group in accordance with P.A. 345 Signed by Glenn E. Richard	Date Sept. 24, 1999
Glenn E. Richard	

Surveyor's Michigan License No. 13040