JAN 2 0 2000

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970, IRER 1 PAGE 316

For corners in			LENAVEE COUNTY
<u>Lenawee</u> (County)	Located In:	Corner Code #	FILED
1. Public Land Survey	T <u>-5-S</u> R <u>-5-E</u> T R T R	<u>G-5</u>	14 JUL 1999 6:31:22 PM VICTORIA J. DANIELS REGISTER OF DEEDS
Property Controlling in Section S Miscellaneous S Property in Sec S	T R T R		Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		3 3 4 4 3 2 1
do hereby certify that under require lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a above were in conformance with Court of Law; established, rexpressed below:	uirements of P.A. 74, Michigan F conformance with regulations of the United States Deptions of the United States Deptions of Law and/or that the conthe rules of the Michigan Boar re-established, monumented, in	survey on July 6, 19 9 A. of 1970, the corner points mentic and rules therefore as required in artment of the Interior, Bureau of L orner points mentioned in lines 3, 4 ai rd of Land Surveyors or by a Decree re-monumented, recovered, found	oned of the and 7 and 7 and 5 8 19 20 21 22 23 24 of a s 10 30 29 28 27 26 25
NOTE: Not more than 4 co on this certificate.		wn and range, may be record	ed 12 31 32 33 34 35 36
 A Description of original r 	nonument and accessories	and/or subsequent restoration	•

G.L.O. 1819 Joseph Fletcher set post cor. Sec. 9, 10, 15 & 16 Elm 12 S 5 E 16 Elm 13 S 20 W 12 1930 Notes on survey by W.E. Frazier describe the corner as "Lost"

1968 W. E. Frazier & Associates did a survey in Sec. 15 & sighted to point in intersection without monumentation

1973 W.E. Sommer re-established the corner and recorded it in Liber 2, Page 321 (location of 1968 by W.E. F. & Associates may be different) (L 2, P 321 states IP but field notes state iron pin)

1974 W. E. Frazier & Associates found iron bar

1990 W.E. Frazier & Associates did survey in SE corner of the NE 1/4 of Section 16 and sighted to the recorded corner.

1997 I found a 1" X 9" iron bar under newly layed asphalt pavement, replaced it with a 3/4" X 3' iron pipe and set a monument box

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.

July 6, 1999 Found 3/4" iron pipe in monument box. Drove the iron pipe down with 5/8" X 3' re-rod inside of it and capped with Lenawee County Re-mon cap stamped P.S. 13040

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner

N.E. cor. of conc. curb under guard rails N 75° W 49.33 S.E. cor. of conc. curb under guard rails S 80° W 49.36 Cut "X" on CMP N 15° W 68.15 Cut "X" on CMP N 25° E 75.93 Survey mark spike & re-mon tag in E.P. S 35° E 58.71 fd dbl hd nail & disc in T.P. S 45° W 41.97

MICHIQ 4 GLENN E. RICHARD No. 13040 SPONAL ST WHITE HERE

Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Glenne Richard	Date _	June 22, 1999
Signed by Slame Ruland Do			