The San San See a go ag g co

Filed under Remonumentation Act 345 of 1990

JAN 2 5 2000

## LAND CORNER RECORDATION CERTIFICATE

SECTION	Filing Requ	uirement of Act 74, Mich. P.A	. 1970 LIBER 1 PAGE 319
For corners in	ocated in:	Corner Code #	STATE OF MICHIGAN LENAWEE COUNTY FILED
1. Public Land Survey	<u>-5-S</u> R <u>-5-E</u> R	G-8	14 JUL 1999 6:32:00 PM
2. Property Controlling S T in Section S T T S. Miscellaneous S T Property in Sec S T	R R R R R R R R		VICTORIA J. DANIELS REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Pla			A B C D E F G H I J K L M
do hereby certify that under requirements in lines 1 and 2 above were in conformal current manual of survey instructions of the Management or by a decree of a Court of Labove were in conformance with the rules Court of Law; established, re-established expressed below:	of P.A. 74, Michigan P.A. nce with regulations and the United States Depart aw and/or that the corner of the Michigan Board of the M	of rules therefore as required in the ment of the Interior, Bureau of Lander points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	4     7     8     9     10     11     12       5     6     18     17     6     15     14     13       7     19     20     21     22     23     24       9     10     30     29     28     27     26     25       11
NOTE: Not more than 4 corners, a on this certificate.	all in the same town	and range, may be recorded	12 31 32 33 34 35 36 13
Couldn't find any informat 1958 Kenneth Suydam s of R.O.W. irons on a lot to 1964 I found a iron pipe of corner of Section 21 1967 The boat spike was boat spike in face of E.P. 1973 W.E. Sommer foun 1974 W.E. Frazier & Ass	cher set 1/4 Sec. p tion on this corner i et a boat spike in li o the north on the e on west R.O.W. & s gone. I set a iron west 36.14 d iron pipe & recon	ost Hickory 9 S 44 W 11 Hick in all of the old survey records. ne of fence to west on the sout east side of the road which he set a boat spike 33' east at recorpipe by same method I used inded it in L 2 P 469 pipe	herly extension surveyed in 1955 ord angle from SE
	K 19" iron pipe in m	applied in restoring or reestablish nonument box. Replaced it with P.S. 13040	•
C. Description of monument for co	rner and accessories	established to perpetuate locating	g the position of the corner:
5/8" X 3' re-rod with Lenavacepted as the best avail	wee County Re-mo lable evidence of t	n cap stamped P.S. 13040 in r he position of the original come	er
Fd. small boat spike in factories and the spike factories and the spike in the spike in factories and	60° W 108.29 65° E 144.14 V 70° E 142.24	/ 36.29	GLENN E. RICHARD No. 13040
		^ <i>/</i> . <i>/</i> ? <i>/</i>	The state of the s

Ratified by Peer Group in accordance with P.A. 345 Co. Rep Jane Rechard Date June 22, 1999

Signed by Sleun Chichard Date July 8, 1999
Glenn E. Richard

Surveyor's Michigan License No. <u>13040</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971