NOV 07 1994

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 29

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

20 Mileur	A CHES. B. ADE AL. A	, 4:										<i>a</i>)
For corners in	1		Corner Code #		FILED 10:56 AM							
<u>Lenawee</u>		Focar	ed In:	Comer Code #	ı			•	11 Miles	C) Eagl	-30 °	
(County)								OCT	28	1994	١٠	
1. Public Land Survey		Т-6	S R-3-E	_B-3				,		• •		
7. Tubilo Edita Galvo,			R	=	1			LENAV	VEE CO	YTAUC		
		_			į			JEANE	בוב"ם.	NOX		
			R				ŀ	ŒGIST	ER OF	DEEDS	į.	
			R									
2. Property Controlling	s	T	R		Į.							
in Section	S	T	R		l Re	giste	er of I	Deeds	Stam	p & Fil	e Nur	nber
3. Miscellaneous	S	T	R		L							
Property in Sec.	S	T	R									
• •						A	В	C D	E F (G H I	ı J	K L M
						1			· · · · · · · · · · · · · · · · · · ·			
4. Lot No	Record	led Plat _			····-	2	6	\$	-	3	+	
5. Private Claims			·-··			3	-	 		$\vdash\vdash$	 	
						4	_ }_	1-8-	<u> </u> 9	10	- 11	12
						5						
						- T					١ ا	
ı, Glenn E. Richard			, in a field	survey on <u>October 6</u>	19 <u>94</u> ,	6	-18	17-	1-76-	15	14	13
				P.A. of 1970, the corner points		7		 	 	 	\vdash	++-1
in lines 1 and 2 above we	ere in co	onformance	e with regulations	s and rules therefore as requ	uired in the	В	19-	20	 2∤1	22	23	24
		646-1	Inited Clates Do	nationant of the Inforiar Burga	⊫ ∧fland	,		1	1	1)	1 1	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Description of original monument and accessories and/or subsequent restoration:

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

G.L.O. January 1824, John Mack set 1/4 post W. Oak 12 N 42 E 8, W. Oak 8 South 24 J.L. Richard records from early 1900's called for iron and tile. 1933 W.E. Frazier found corner 2 1/2' deep and set spike near surface 14" Elm N 23° E 60'. May 1962, I dug and found spike and raised it to the surface of the pavement. June 1965 I found a boat spike which checked the remaining witness and an iron pipe @ the 1/8 corner 1335' South. Nov. 1971, W.E. Sommer found the boat spike and recorded it in L. 1, P. 69, Dbl hd. nail in Elm stump N 25° E 60.20. March 1982, W.E. Sommer found iron pipe in monument box which checked to 1/8 corner South as found on the 1965 survey.

10

11 12 13

Description of corner evidence found and/or method applied in restoring or reestablishing corner: В.

October 6, 1994, Found iron pipe in monument box which checked witnesses taken on the March 1982 survey.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

3/4" X 3' iron pipe capped G.E.R., P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner. cut "X" cut on C.M.P. N 50° W 36.84 Cut "X" cut on C.M.P. N 50° E 38.18 NW edge of gas line valve box S 50° E 47.24 Set dbl. hd. nail & disc in 10" Pine S 20° E 70.75



	MARIE SONAL SURVEY
Ratified by Peer Group in accordance with P.A. 345 Signed by Lenn & Richard Glenn E. Richard	Co. Rep. Alexand Date October 13, 1994 Date Oct 20, 1994
Surveyor's Michigan License No. 13040	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
	REVISED MAY 14, 197 REVISED JAN., 196 ADAPTED FOR WORD PROCESSING MARCH, 198