SUFVEY & REMONINENTATION

NOV 07 1994

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 33

COMMISSION

For corners in Lenawee (County)	Located In:	Corner Code #	FILED 10:56 AM
1. Public Land Survey	T <u>-6-S</u> R <u>-3-E</u> TR TR	<u>F-3</u>	OCT 28 1994 LENAWEE COUNTY JEANETTE D. MNOX REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, F	S T R		A B C D E F G H I J K L M 2 6 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
do hereby certify that under in lines 1 and 2 above wer current manual of survey ins Management or by a decree above were in conformance Court of Law; established expressed below:	requirements of P.A. 74, Michigan I re in conformance with regulations structions of the United States Dep of a Court of Law and/or that the count the rules of the Michigan Boad, re-established, monumented, corners, all in the same town	survey on <u>October 8</u> 19 9 P.A. of 1970, the corner points mention and rules therefore as required in partment of the Interior, Bureau of La orner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of re-monumented, recovered, found and range, may be recorded	ned 7 the 8 19 20 21 22 23 24 and 5 9 of a 10 30 29 28 27 26 25
		and/or subsequent restoration:	

G.L.O. January 1824, John Mack set 1/4 Sec. post W. Ash 15 S 3 E 15, B. Walnut 30 N 30 W 24 J.L. Richard record from 1914 "Found stone, fence post South 39 links, set stone on line between at 1/2 distance between E-3 and F-3.

April 1976, I dug but couldn't find any trace of the stone. Dug at the 1/8 corner and found the stone surrounded by pieces of tile, Set 3/4" X 4' galv pipe by doubling the distance and extending the line east from the SW corner of Section 4 and the found 1/8 corner and recorded them in L. 3, P. 425.

"X" cut on C.M.P. S 70° E 80.35

Dbl hd. nail & disc in Tel. pole S 15° W 27.65

Dbl hd. nial & disc in Elec pole S 25° E 77.18

Dbl hd. nail & disc in Elec. pole N 10° E 87.66

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 10, 1994, Found iron pipe in monument box, top of box missing; Top of iron hit and bent. Replaced iron with 3/4" X 3' iron pipe capped G.E. R. P.S. 13040.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' from pipe, capped GER P.S. 13040 in monument box, and is accepted as the best available evidence of the position of the original corner.

Found Dbl. hd. nail & disc in Elec. pole N 10° E 87.56

Found Dbl. hd. nail & disc in Elec. pole \$ 25' E 77.12

Found Dbl. hd. nail & disc in Tel. pole \$ 15° W 27.58

"X" cut on C.M. P. \$80° E 80.58
"X" cut on C.M.P. N 75° E 115.53

	E OF MIC	HOUSE.
Co CONTRACTION OF THE PARTY OF	GLENN E. RICHARD No. 13040	NI STATE OF THE PARTY OF THE PA
ctober 13.	SSIONAL SU	ALC: NO.

Ratified by	Peer Group	in	accordance with I	P.A.	345
Signed by_	Hlen	11	accordance with I	<u>-</u>	

Date Oct. 20,1994

South Carrier of District Confession

The Auditor of the San Comment

Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971