REMONUMENTATION

APR 2 8 1995

on this certificate.

COMMISSION

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 001 PAGE 57

For corners in Lenawee Located in: Corner Code # (County) 2:01 P.M. 1. Public Land Survey T-6-S R-3-E C-3 DEC 05 1994 TENAMEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS 2. Property Controlling S in Section S Т R Register of Deeds Stamp & File Number 3. Miscellaneous Т Property in Sec. A B C D E F G H I J K L M 1 _, Recorded Plat _ 2 5. Private Claims 3 4 5 6 ı, Glenn E. Richard , in a field survey on <u>October 10</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 7 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 8 current manual of survey instructions of the United States Department of the Interior, Bureau of Land 9 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 10 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 29 28 Court of Law; established, re-established, monumented, re-monumented, recovered, found as 11 expressed below: 12

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

G.L.O. January 1824, John Mack set post cor. Sec. 3, 4, 9 & 10 W. Ash 10 N 62 W 24, W. Oak 24 S 64 E 34. October 1880, James Blair survey notes "I found a stake & large stone".

J.L. Richard record from early 1900's call for stake & large stone.

June 1959, K.L. Suydam "Found large pointed stone about 1' below surface, raised with drag tooth, spike & washer in 20" Hickory N 59° E 64.95, 30" Elm N 35° W 44.80, 26" Maple S 24° E 52.00, 26" Maple S 49° W 46.00. March 1976, I probed through the pavement at point located from remaining witnesses and set with 3/4" Iron pipe and recorded it in L.3, P. 423, Dbl. hd. nail & disc in: Tel. pole N 35° W 44.84, 20" Hickory N 65° E 65.70.

13

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 10, 1994, Found 1/2" rod over 3/4" X 12" iron pipe. November 16, 1994, Found 1/2" re-rod at surface over 3/4" X 12" iron pipe. Replaced re-rod and 3/4" iron pipe and set 3/4" X 3' iron pipe in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. dbl. hd. nail & disc in Tel. pole N 35° W 44.87 Set dbl. hd. nail & disc in Elec. pole N 25° W 94.93 Set dbl. hd. nail & disc in Elec. pole \$ 40° E 71.34 Set 60d spike in 40" Maple S 30° W 72.82 Cut "X" on C.M.P. N 40° E 38.42



Ratified by Peer Group in accordance with P.A. 345 Signed by Sun & Luland	Co. Rep. Hann & Richard Date Nov. 29,1994	Date_ <u>October_13, 1994</u>
Glenn E. Richard	,	