JAN2 5 2000

SECTION

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF HICHIGAN LENAMEE COUNTY FILED

Ear corners in			( ,
For corners in Lenawee (County)	Located In:	Corner Code #	14 JUL 1999 6:30:31 PH
1. Public Land Survey	T <u>-6 - S</u> R <u>- 4 - E</u> T R T R	_A - 12	VICTORIA J. DANIELS REGISTER OF DEEDS
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec</li> </ol>	T R R S T R S T R R S T R R S T R R S T R R S T R R S T R R S T R R S T R R R R		Register of Deeds Stamp & File Number
I, Glenn E. Richard do hereby certify that under In lines 1 and 2 above were current manual of survey ins Management or by a decree above were in conformance Court of Law; established expressed below:  NOTE: Not more than on this certific:  A. Description of origin  G.L.O. This po 1875 Burton K 5.28 chains (34)	requirements of P.A. 74, Michigan P.A e in conformance with regulations are structions of the United States Depart of a Court of Law and/or that the cornwith the rules of the Michigan Board of, re-established, monumented, re-4 corners, all in the same towarte.  A corners, all in the same towarte.  The property of the	arvey on June 21, 19 99, A. of 1970, the corner points mentioned at rules therefore as required in the transport of the Interior, Bureau of Land er points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as an and range, may be recorded and/or subsequent restoration:	
B. Description of corne	er evidence found and/or method	applied in restoring or reestablish	ing corner:

April 27, 1999 I re-established the comer on line between the W 1/4 comer and NE comer of Section 36 T6S R3E and at the record jog shown on Burton Kent's 1875 survey. The corner falls 5.5'± South of the pavement.

June 21, 1999 Set 30" Harrison monument

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison monument stamped P.S. 13040. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

spike & re-mon tag in 26" Oak S 10 W 26.47 spike & re-mon tag in T.P. West 84.52 P.K. re-mon tag in Top of guard rail post N 10 E 29.29 Survey mark spike & re-mon tag in T.P. S 55 E 21.88 Carsonite post South 5.0 M-11 North 348.48



	•		74	V
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Hennt Richard	_Date _	June 22, 1999	_
Ratified by Peer Group in accordance with P.A. 345  Signed by <u>Slaven E. Ruchard</u> Di  Glenn E. Richard	ate July 8,1999			
Glenn E. Richard				

Surveyor's Michigan License No. <u>13040</u>