## SURVEY & REMONUMENTATION

Filed under Remonumentation Act 345 of 1990

SEP 0 3 1996

1. Public Land Survey

5. Private Claims \_

expressed below:

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 107

COMMISSION			riery O
For corners in			
Lenawee	Located In:	Corner Code #	Print :
(County)		İ	FIL

T-6-S R-4-E

2. Property Controlling S т

AUG 08 1996 LENAWEE COUNTY
JEANETTE D. KNOX
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

in Section 3. Miscellaneous S Т R Property in Sec. S Т 4. Lot No. , Recorded Plat

I, Glenn E. Richard , in a field survey on JUIV 10 19 96 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

6 7 8 9 Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G.L.O. June 1819, Joseph Fletcher set 1/4 post Lynn 16 N 77 W 14, Lynn 10 S 81 W 9 Oct. 1841 S.C. Boughton County surveyor subdivided Section 25, Town 6 South, Range 4 East but didn't describe any of the monumentation

May 3, 1882 James Blair "found stone"

Early 1900's J.L. Richard records call for stone

May 25, 1968 I dug but didn't find any stone. I set an iron pipe by extending line west and by doubling the distance measured between stones called for in J. Blair survey of 1885 at the Northeast corner of the Section and the NW corner of the NE 1/4, NE 1/4, Section 36

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 10, 1996 Found iron pipe as set in 1968. Removed and set 30" Harrison monument.

Note: The corner is 2' ± West of the west edge of the 5' C.M.P. which runs NW-SE

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison monument stamped P.S. 13040 and is accepted as the best available evidence of the position MINIMUM OF MICKING of the original corner.

Cut "X" on 5' C.M.P. S 55° E 20.67

Dbl. hd. nail & disc in east face of Elec. pole \$ 05° W 29.06

Cut "X" on 5' C.M.P. N 30° W 31.01

Dbl. hd. nail & Re-Mon tag in South face of electric meter pole N 85 E 305.42

A SHIRING	E OF MICH	MINNING AS HELL
AMMINIMINIMINIMINIMINIMINIMINIMINIMINIMI	GLENN E. RICHARD No. 13040	Thumannian
7-16-96	SONAL SU	William Sold Sold Sold Sold Sold Sold Sold Sold

Ratified by Peer Group in accordance with P.A. 345

Co. Rep. Hann & Ruhand

bun & Richs Glenn E. Richard

Surveyor's Michigan License No. 13040