REMONUMENTATION

APR 2 8 1995

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 48

For corners in	•		
Lenawee (County)	Located in:	Corner Code #	FILED
1. Public Land Survey	T <u>-6-\$</u> R <u>-5-E</u> TR TR	E - 10	DEC 05 1994 2:01 P.IT
in Section	TR STR STR		REGISTER OF DEEDS Register of Deeds Stamp & File Number
3. Miscellaneous Property in Sec.	S T R S T R		ABCDEFGHIJKLM
	ecorded Plat		1 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5
do hereby certify that under to in lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance w	, in a field requirements of P.A. 74, Michigan in conformance with regulations ructions of the United States De of a Court of Law and/or that the with the rules of the Michigan Bo re-established, monumented,	P.A. of 1970, the corner points no s and rules therefore as requir partment of the Interior, Bureau corner points mentioned in lines 3 ard of Land Surveyors or by a De	nentioned 7 red in the 8 19 20 21 22 23 24 10 5 4 and 5 10 29 28 27 26 25
NOTE: Not more than 4 on this certificate	corners, all in the same town	and range, may be recorded	

Description of original monument and accessories and/or subsequent restoration:

G.L.O. August 1819, Joseph Fletcher set 1/4 post, B. Ash 12 N 30 E 6, Maple 6 S 39 E 9.

August 1881, James Blair found stake and set a new one.

January 1986, I found two C.M.P.'s under the road next to location of the corner. Set 5/8" X 24" iron rod in line wit occupied line from West (center line of ditch east) by doubling the distance between the occupied Center of Sec. 29 and the occupied 1/8 corner and record distance from the N-S 1/4 line in Section 28 and recorded it in L.5,

P.159 Cut "X" on C.M.P. N 45° W 26.55 Cut "X" on C.M.P. N 80° E 29.67

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

May 1994, Found 5/8" rod as recorded in L.5, P. 159

The James Blair survey of Section 28 doesn't show any distances North or South from this corner.

June 17, 1994, I dug with a back hoe at the N. 1/4 corner and found the N. 1/4 corner and computed the center of the section. My computed distance, from the computed Center of the Section, is 1.5 shorter than Blair 1881

October 24, 1994, Replaced the 5/8" rod with a 30" Harrison monument stamped P.S. 13040, and found no virgin sc due to the close proximity to the C.M.P.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

30" Harrison monument stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Fd. "X" on C.M.P. N 30° W 26.59

Fd. "X" on C.M.P. N 85° E 29.73

NE Cor. of brick house \$ 40° E 163.92

NW Cor. of brick house \$ 30° E 148.71

SW Cor. of brick house S 20° E 192.32

Corner is 2' East of West edge of gravel road

Corner if 6' North of the Center of the E.W. 48" C.M.P.

SONAL SUP Co. Rep. Glann Che Date November 3, 1994 Ratified by Peer Group in accordance with P.A. 345 Tlenn E Richard _ Date *Nov. 11,199* 4 Signed by_ Glenn E. Richard

Surveyor's Michigan License No. _13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1

CHAILING HALLING

OF

GLENN E.

RICHARD

No. 13040

MICH