SURVEY & REMONUMENTATION

SEP 0 3 1996

Filed under Remonumentation Act 345 of 1990 RAGE 101

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

				<i>M</i> ¹ ′′			
For c	orners in			FILED 11.30 APP			
_ Len	awee	Located In:	Corner Code #	C,/), UJJI			
	(County)	•		IIIN * 1000 //			
				JUN -4 1996 '			
1. P	ublic Land Survey	T <u>-6-\$</u> R <u>-5-E</u>	<u>E - 13</u>	LENAWEE COUNTY			
		T R		JEANETTE D. KNOX			
		TR		REGISTER OF DEEDS			
		T R					
		S T R					
		S T R		Register of Deeds Stamp & File Number			
		S R					
P	roperty in Sec.	S T R					
				ABCDEFGHIJKLM			
				1			
		ecorded Plat		2 6 5 4 3 2 1			
5. P	rivate Claims			3			
				4 - 7 - 8 - 9 - 10 - 11 - 12 -			
				5			
	onn E Bichard	, in a field s	survey on October 2/1 199	35 6 18 17 16 15 14 13			
i, <u>U</u>	erill E. Kiulaiu	requirements of P.A. 74, Michigan	P.A. of 1970, the corner points mer	ationed 7			
in line	es 1 and 2 above were	in conformance with regulations	and rules therefore as required	in the 8 19 20 21 22 23 24			
currer	nt manual of survey inst	ructions of the United States Der	partment of the Interior, Bureau of	fLand			
Mana	gement or by a decree of	of a Court of Law and/or that the o	orner points mentioned in lines 3, 4	anus			
above	were in conformance v	with the rules of the Michigan Boo re-established, monumented,	re-monumented recovered fou				
expressed below:		te-established, monumented,	to monamenta, recorded, rea				
•				"" T T T T T T T T T T			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded							
	on this certificate	÷.					
_	and the second		and/an aubannant restaratio	n.			
A.	Description of origin	nal monument and accessories	and/or subsequent restoration	11.			
	G.L.O. 1815, Alex Holmes set post corner Sec. 32 and 33 Ash 6 N 60° E 4, Elm 18 S 87° W 10 Dec. 1884, James Blair did a survey in Section 4, T7S-R5E and shows the jog of 48 links West of the NW corner of Section 4.						
	Couldn't find any surveys of anyone ever finding or re-establishing this corner until I did in 1973. I re-established the NW corner of Section 4, T7S-R5E using information of J.L. Richard's records in Section 5, T7S-R5E and set an iron						
	the NW corner	of section 4, T7S-R5E using	information of J.L. Richard	's records in Section 5, 175-R5E and set an iro			
	pipe 48 links We	est for E-13, T6S-R5E and re	corded it in L. 2, P. 343.				
В.	Description of corne	er evidence found and/or meth	od applied in restoring or rees	stablishing corner:			
	October 400E	Equal iron pine 4" below 6	urface of navement. Didn	't find anything else while digging to set			
		October 1995, Found iron pipe 4" below surface of pavement. Didn't find anything else while digging to set monument box.					
	Replaced FIP	Replaced F.I.P. with 3/4" X 3' gas pipe capped G.E.R. P.S. 13040 and set monument box over fron pipe.					
	James Blair rec	ord East to F-13, T6S-R5E is	2644.95, measured 2644.41				
		·					
			•				
C.	Description of many	iment for corner and accesso	ries established to pernetuate	locating the position of the corner:			
C.	peacification of mone	ament for comer and decessor	Total and to polybridate				

3/4" X 3' gas pipe capped G.E.R. P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

"X" cut on South end C.M.P. S 70° W 57.42 "X" cut on North end C.M.P. N 40° W 32.85 "X" cut on North end C.M.P. N 15° W 31.34

"X" cut on South end C.M.P. S 55° E 46.87

Surveyor's Michigan License No. 13040

Dbl. hd. nail & disc in 12" Cedar N 20° W 91.88

Dbl. hd. naíl & disc in Elec. pole S 30° W 20.43

E-1, T7S-R5E (NW corner Section 4) East 31.68

MINIME OF HICAN MAN SAIE OF MICHIGA GLENN E. RICHARD THE TEST ONAL SURVEY

	$\alpha A + A A$	
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Henne Richard	Date_ <u>12 - 18 - 95</u>
Signed by Henry & Richard	Date 1-15-96	
Glenn E. Richard	· · · · · · · · · · · · · · · · · · ·	