OCT 1 9 1998

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

PAGE 285
STATE OF MICHIGAN
LENAWEE COUNTY

For corners in			FILED
Lenawee	Located In:	Corner Code #	
(County)			25 SEP 1998 1:15:53 PM
1. Public Land Survey	T <u>- 7 - S</u> R <u>- 3 - E</u> T R T R	F-3	VICTORIA J. DANIELS REGISTER OF DEEDS
2. Property Controlling S in Section S	TR		
3. Miscellaneous S_ Property in Sec S	TR		Register of Deeds Stamp & File Number
I, Glenn E, Richard do hereby certify that under requir in lines 1 and 2 above were in courrent manual of survey instruction Management or by a decree of a Corabove were in conformance with the	, in a field su rements of P.A. 74, Michigan P.A. rements of P.A. 74, Michigan P.A. rements of the United States Depart report of Law and/or that the corn report of the Michigan Board	arvey on <u>September 16, 19 98,</u> A. of 1970, the corner points mentioned not rules therefore as required in the intent of the Interior, Bureau of Land er points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	7 8 19 20 21 22 23 24
expressed below:			10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			12 31 32 33 34 35 36 13
A. Description of original m	onument and accessories a	ind/or subsequent restoration:	
GLO 1924 John M	ullatt Sat 1/4 past Sugar	- C N 4C 1/2 E 21 Higher 12 6	2.40 E 24

GLO 1824 John Mullett Set 1/4 post Sugar 6 N 46 1/2 E 21 Hickory 12 S 19 E 21 Could not find any information on this corner in any of the old survey records 1977 I set a P.K. nail in the pavement in line with the occupied fence lines N & S and on line between E-3 and G-3 T7S R3E and recorded it in L 3, P 527. 1996 Associated Engineers & Surveyors found P.K. nail 6" deep and raised with P.K. nail Dbl hd nail & disc in E.P. N 30° E 51.44, Dbl hd nail & disc in E.P. S 20° E 48.21,

Iron pipe South 50.00.
1996 Donald Bendzinski (P.S. 35989) dug and found P.K. nail in pavement and another 3" deeper. Dug through the concrete pavement but found nothing else. Set 3/4" iron pipe in monument box and recorded it in L 5 P 333.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 13, 1998 I found iron pipe (capped D.B. P.S. 35989) in monument box set in new asphalt pavement. Record distance east to G-3=2673.13 Meas. 2673.20 Angle from G-3 to F-3 to iron pipe South=90°19'18" Record=90°19'55" Distance West to E-3=2663.31 Sept. 16, 1998 Replaced the iron pipe with a 5/8" X 3' re-rod with a Lenawee County Re-mon cap stamped P.S. 13040 and raised box with ring to present paved surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with a Lenawee County Re-mon cap stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Found dbl. hd. nail & disc in E. face E.P. N 15° E 51.37 Found dbl. hd. nail & disc in E. face E.P. S 35° E 48.15 Iron pipe on 1/4 line South 49.99 SW corner of brick building (TLC) N 65° W 234.20 SE corner of brick building (TLC) N 45° W 167.53

Ratified by Peer Group in accordance with P.A. 345 Co. Republic Related Date September 22, 1998

signed by House Richard Date Sept. 23, 1998
Glenn E. Richard

Surveyor's Michigan License No. \_13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

GLENN E

RICHARD

No. 13040