## SURVEY & REMONUMENTATION

Filed under Remonumentation Act 345 of 199d-IBER 1 PAGE 255

9

10 11

12

13

OCT 1 9 1998

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN LENAWEE COUNTY FILED

		SEC	Į	ION
For corners	in			

expressed below:

Lenawee (County)	Located In:	Corner Code#	15 SEP 1998 8:58:38 AM
1. Public Land Survey	T <u>-7-\$</u> R <u>-3-E</u> TR TR	H-3	VICTORIA J. DANIELS REGISTER OF DEEDS
- 12F211) 11111-11111-12	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Red 5. Private Claims			A B C D E F G H I J K L M
in lines 1 and 2 above were in current manual of survey instru	, in a field su quirements of P.A. 74, Michigan P.A n conformance with regulations an ictions of the United States Depart a Court of Law and/or that the corne	d rules therefore as required in ment of the Interior, Bureau of L	oned 6 18 17 6 15 14 13 and 7

on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

GLO 1824 John Mullett set 1/4 Sec. post Lynn 20 N 20 E 34 Beech 6 S 14 E 18

Early 1900's J.L. Richard's record iron spike

1925 Beecher Road survey called for "Iron bar = 1/4 Sec. corner 71.0 feet South of R.R. track centerline"

1936 The corner is the point of beginning for Assessor's Plat No. 16, City of Adrian

1964 Point of beginning Plat of Lincoln Square

1970 Point of beginning Plat of Brookside

1997 Donald Bendzinski recorded found iron bar in monument box in L 5 P 335

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 2, 1998 I assisted the paving contractor with raising the monument box.

July 15, 1998 I found the "iron bar" to be leaning to the east. The "iron bar" was a piece 20" X 2 1/4" X 1/2" strap iron of the type that was used on top of wood logs that the original railroads ran on. Dug deeper and found the bottom was in the center of a tile standing on end. I set a 5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040 in a monument box and is accepted as the best available evidence of the position of the original corner

Fd. mag nail in S. face of E.P. N 65° E 91.76 Fd. mag nail in E. face of E.P. N 15° W 107.73 NE corner Holsum Thrift Store S 60° E 148.09 NW corner Holsum Thrift Store S 50° E 119.83 NW corner of brick building S 50° W 109.36 Centerline of R.R. tracks North 70.85 GLENN E. RICHARD No. 13040 &

Ratified by Peer Group in accordance with F	.A. 345 Co. Rep. J. Bunch Richard Date July 21, 1998	
Signed by Silver & Polland	Date Aug 75 1998	

Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971