## **SURVEY &** REMONUMENTATION

JAN 1 5 1998

Filed under Remonumentation Act 345 of 1990

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Lenawee (County)	Located In:	Corner Code#	STATE OF WICHIGAN LENAWEE COUNTY FILED
1. Public Land Survey	T <u>-7 - S</u> R <u>- 4 - E</u> T R T R	M-6	17 OCT 97 3:53 P.M. Victoria J. Daniels
Property Controlling S_ in Section S_     Miscellaneous S_ Property in Sec S_	T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R		REGISTER OF DEEDS  Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat			3 4 7 8 9 10 11 12 5 6 18 17 6 15 14 13 4
Management or by a decree of a Co above were in conformance with the	ourt of Law and/or that the come rules of the Michigan Board	tment of the Interior, Bureau of Land her points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a -monumented, recovered, found as	7 8 -19 20 21 22 23 24 9 10 30 729 28 27 26 25
NOTE: Not more than 4 cor on this certificate.	ners, all in the same tow	n and range, may be recorded	11 12 31 32 33 34 35 36
A. Description of original mo	nument and accessories a	and/or subsequent restoration:	
1882 James Blair "F 1889 James Blair F	Fletcher set 1/4 Sec. po Found Stake and bricks" ound Stake and "Set nev r "Found old stake & bric		ch 12 S 55 E 19

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

1984 Werner Sommer "Found iron pipe" and recorded it in L 5, P 136.

Set 1" X 4' iron pipe capped 12030

Sept. 4, 1997 I found a 3/4" X 40" iron pipe which checked the recorded witnesses and replaced it with a 3/4" X 3' iron pipe capped G.E.R. 13040. Saw traces of the brick when I removed the found iron pipe. Sept. 6, 1997 Set monument box after Len. Co. Rd. Comm. layed new asphalt pavement,

1973 Assoc. Eng. & Surveyors dug large hole (iron was gone) Found bricks & dark spot and rust from iron.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Found dbl hd nail & disc in H-frame pole S 85° W 34.66 Found dbl hd nail & disc in H-frame pole S 60° W 39.70 Found dbl hd nail & disc in H-frame pole S 25° W 83.02 Found dbl hd nail & disc in R. R. tie post N 65° E 27.63 3/4" iron pipe in monument box at A-6 T7S R5E North 12.55

The state of the s SHIE OF MICHIGP GLENN E. RICHARD No. 13040 ROBIONAL SUP

$\Lambda \Lambda$	
Ratified by Peer Group in accordance with P.A. 345 Co. Rep	hard Date Sept. 30, 1997
Signed by Skint Richard Date Oct. 7, 1997	
Glenn E. Richard	
Surveyor's Michigan License No. <u>13040</u>	FORM APPROVED BY MICHIGAN STATE BOARD OF LA