

NOV 07 1994

## Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 05

COMMISSION

	corners in nawee (County)	Located In:	Corner Code #	FILED 2:59 P.M. OCT 10 1994	
1. [	Public Land Survey	T <u>- 7 - S</u> R <u>- 5 - E</u> T R T R T R	к-13	OCT 10 1994  LENAWEE COUNTY JEANETTE D. MNOX REGISTER OF DEEDS	
i 3. I	n Section Miscellaneous	STR STR STR		Register of Deeds Stamp & File Number  ABCDEFGHIJKLM	
I, _Q do h in lin curre Mana abov Cour expre	lenn E. Richard ereby certify that under les 1 and 2 above were int manual of survey insigement or by a decree of ewere in conformance of t of Law; established essed below:  E: Not more than 4 on this certificate	, in a field s requirements of P.A. 74, Michigan F e in conformance with regulations tructions of the United States Dep of a Court of Law and/or that the co with the rules of the Michigan Boa , re-established, monumented,  corners, all in the same town	curvey on Sept 23 1994.  P.A. of 1970, the corner points mentione and rules therefore as required in the lartment of the Interior, Bureau of Landorner points mentioned in lines 3, 4 and and of Land Surveyors or by a Decree of re-monumented, recovered, found a land range, may be recorded and/or subsequent restoration:	1 2 3 2 1 3 2 1 3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 16 8 6 9 10 30 29 28 27 26 25	
	G.L.O. 1819, Joseph Fletcher set post Elm 9 S 40 W 5, Cottonwood 12 N 20 W 8  September 19, 1883, on a survey by James Blair "Corner stake found"  November 3, 1886, James Blair called for stake under stone 14 links east of bridge.  J.L. Richard records from early 1900's called for stone and stake.  The bridge was there in 1958 during the road survey but the corner wasn't found and I set a 3/4" rod at the record jog west from the stone I found at the NE corner of Section 2, T8S-R5E.  May 1972, Found iron and Werner Sommer recorded it in L. 1, P. 367.  June 1984, dug and found the 3/4" rod and raised to surface with 1 1/4" X 9" iron pipe.				
В.	August 29, 1994, F Also found a 3/4" i	ound the 1 1/4" iron pipe. iron bar 4.96 N 70° 42' E (90	od applied in restoring or reestabli 1º 00' sighting to S 1/4 corner, S 2 with 3/4" X 3' iron pipe in mor	Sec 36, T7S-R5E).	
C	Description of many	ment for corner and accessor	ies established to perpetuate local	ting the position of the corner	

Description of monument for corner and accessories established to perpetuate locating the position of the corner

3/4" X 3' iron pipe capped 13040 in monument box and is accepted as a careful and faithful reestablishment of the position of the original corner.

NW corner of SW wingwall of original bridge (only one left) S 70° W 29.40 "X" cut on C.M.P. N 10° W 33.38 "X" cut on C.M.P. S 60° E 44.95 NW corner of house found. S 60° E 158.19 Dbl. hd. nail & disc in base of old Elec Pole N 70° E 103.49 NE corner of Section 2, T8S-R5E, East 75.15

TO THE OUTER MARKET AND THE CONTROL OF

Surveyor's Michigan License No. \_13040

Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Glenn & Richard Date 9.15-94
Ratified by Peer Group in accordance with P.A. 345 Signed by Sun Charle	Date <u>October 3, 1994</u>
Glenn E. Richard	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

15、通知技术会从各位的。

GLENN E.

RICHARD

No. 13040