



Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 66

For corners in			CII Po	
Lenawee (County)	Located In:	Corner Code #	FILED 3:19pm	
1. Public Land Survey	T <u>-8-S</u> R <u>-3-E</u> TR TR TR		MAK 14 1995 LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS	
 Property Controlling in Section Miscellaneous 	S T R S T R S T R		Register of Deeds Stamp & File Number	
Property in Sec.	S R		A B C D E F G H I J K L M	
	Recorded Plat		1 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5	
do hereby certify that under in lines 1 and 2 above we current manual of survey in Management or by a decree above were in conformance	requirements of P.A. 74, Michigan re in conformance with regulations structions of the United States De of a Court of Law and/or that the swith the rules of the Michigan Bo	survey on August 2 19 94 P.A. of 1970, the corner points men s and rules therefore as required partment of the Interior, Bureau of corner points mentioned in lines 3, 4 ard of Land Surveyors or by a Decre re-monumented, recovered, four	tioned 7 in the 8 19 20 21 22 23 24 Land and 5 ee of a 10 30 29 28 27 26 25 and as 11 12 31 32 33 34 35 36	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.				

- Description of original monument and accessories and/or subsequent restoration:
 - G.L.O. March 1824, John Mullett set 1/4 Sec. post Sugar 12 S 56 W 9, W. Ash 16 S 63 E 24.

April 1940, during a road survey by Harold Clegg, R.L.S. 13578, he put a note in J.L. Richard record book "Found corner (no description) set irons 33' North & 33' South.

Jan 4, 1972, We dug and found iron pipe 4' deep, raised to surface with 3/4" iron pipe and recorded it in L.1, P. 145 (PK. nail & disc in Elec. pole N70° E 88.70 same in all three recordings).

W.E. Sommer, recorded it in L. 4, P. 288, and I recorded it again in L. 5, P. 178.

June 10, 1993, The road was under construction & the iron pipe was gone.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 2, 1994, Steve Young, P.S. 25885, set P.K. nail in pavement by extending the west line South from the found Plat monuments of Lot 12, Plat of Jafet Acres as recorded in Liber 17, Pages 56 & 57, Lenawee County Records. December 8, 1994, Set 3/4" X 3' iron pipe capped P.S. 13040 in monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Plat monument North 60.00

Plat monument North 330.00

cut "X" on C.M.P. \$ 60° W 56.98

Cut "X" on C.M.P. N 70° W 57.42 Cut "X" on C.M.P. N 55° E 33.85

Surveyor's Michigan License No. <u>13040</u>

Fd. P.K. nail & disc in Elec. Pole N 75° E 88.70

Dbl. hd. nail & disc in east face corner post North 23.22

OF MICH GLENN E. RICHARD No. 13040

·	
atified by Peer Group in accordance with P.A. 345	Co. Rep. Slenn & Richard Date November 17, 1994 Date Dec. 21, 1994
igned by Sleun C. Richard	Date Dec. 21, 1994
Glenn E. Richard	