## SURVEY & REMONUMENTATION

**JAN 1** 5 1998

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  Lenawee (County)	Located In:	Corner Code #	STATE OF MICHIGAN FILED FILED
1. Public Land Survey	T <u>-8-S</u> R <u>-3-E</u> T R	<u>G-7</u>	5 NOV 97 11:58 A.H.
Property Controlling S			VICTORIA J. DANIELS REGISTER OF DEEDS
in Section S  3. Miscellaneous S  Property in Sec S	T R R R R R R R R R R R R R R R R R R R		Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		A B C D E F G H i J K L M
i, <u>Gienn E. Richard</u>	, in a field s	urvey on <u>October 23, 19 97</u> ,	3 4 7 8 9 10 11 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			6 18 17 6 15 14 13 7 8 19 20 21 22 23 24
Court of Law; established, reexpressed below:	e-established, monumented, re	-monumented, recovered, found as	9 10 30 29 28 27 26 25
NOTE: Not more than 4 co		n and range, may be recorded	11 12 31 32 33 34 35 36 13
A. Description of original r	nonument and accessories	and/or subsequent restoration:	
1824 John Mullett	set post corner Sections	15, 16, 21 & 22 Beech 8 N 51W	4 Beech 12 S 53 E 29

1908 J.L. Richard Found large stone 2' across 1957 +/- W.E. Sommer set spike from "appr, remains of witnesses"

1966 I found the R. R. spike

1982 Don Olmstead recorded the corner in Liber 5 Page 46 "Found R. R. spike"

1991 Mannik & Smith Engineers found 5/8" iron rod

1993 The road was reconstructed

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

April 3, 1997 I found a 3/4" iron pipe in a monument box which checked my 1966 angle in the SE corner of Section 16 and the angle and distance to the iron pipe I drove 33' N and 33' W of section lines. Oct. 23, 1997 Probed for stone but didn't find any. Capped existing iron pipe G.E.R. 13040

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" iron pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Found iron pipe N 45° W 47.01 Found P.K. nail & disc in W. face E.P. N 15° E 103.79 Found P.K. nail & disc in S. face E.P. N 15° E 103.45 Found P.K. nail & disc in S. face E.P. N 20° E 76.56 dbl hd nail & disc in 22" Hickory S 70° E 107.22 dbl bd nail & disc in E.P. S 10° E 162.80



	No. 13
Ratified by Peer Group in accordance with P.A. 345 Co. Rep Glennt Richard  Signed by Glenn E. Richard  Date Nov. 3, 1997  Glenn E. Richard	Date October 28, 1997
Surveyor's Michigan License No. 13040	FORM APPROVED BY MICHIGAN STATE BOARD OF LA
	ADAPTED FOR WOR