## SURVEY & REMONUMENTATION

JAN 1 5 1998

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1920BER 1 PAGE 214

9

10 11

12

13

## SECTION

For corners in

expressed below:

Lenawee (County)	Located In:	Corner Code #	STATE OF HICHIGAN LENAWEE COUNTY FILED
1. Public Land Survey	T <u>-8-S</u> R <u>-3-E</u> TR_ TR	M-3	17 OCT 97 3:56 P.M.
Property Controlling S_ in Section S_	TR TR		VICTORIA J. DANIELS REGISTER OF DEEDS
3. Miscellaneous S_ Property in Sec S_	TR		Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat		A B C D E F G H I J K L
I, Glenn E. Richard	, in a field su	rvey on <u>July 30 19 97</u>	4 7 8 9 10 11 12
in lines 1 and 2 above were in courrent manual of survey instructi	conformance with regulations an ons of the United States Depart	A. of 1970, the corner points mention of rules therefore as required in timent of the Interior, Bureau of La er points mentioned in lines 3, 4 an	the and 7

on this certificate.

Description of original monument and accessories and/or subsequent restoration:

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

\*NOTE: SEE COMMENTS & SKETCH ON BACK

G.L.O. 1824 John Mullett ran a corrected town line from the south and set post corner Sections 1 & 12 5.26 chains North of the old Section corner by Joseph Wampler W. Oak 18 S 50 W 42 Lynn 7 N 26 W 13 1920 J.L. Richard records show witnesses (all gone) to S.E. corner Section 1 and don't describe type of monumentation

1970 Werner Sommer re-established the corner at record jog north from A-3 T8S R4E on line extended north from M-4 T7S R3E and recorded it in L 1, P 625

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 30, 1997 The pavement had been scarified. I found the bottom of the 3/4" iron pipe set by Werner Sommer. I dug and probed deeper and wider but didn't find anything else. Replaced the found iron with a 3/4" X 3' iron pipe.

Oct. 8, 1997 Set monument box in base course of new asphalt pavement

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E.R. 13040 in a monument box and is accepted as the best available evidence of the position of the original corner.

1

"X" cut on S. end CMP S 50° W 31.77

"X" cut on N. end CMP N 50° E 34.52

Survey mark spike & re-mon tag in E.P. N 10° E 167.34

Found dbl. hd. nail & disc in E.P. S 10° E 160.29

Iron pipe in monument box at A-3 T8S R4E South 297.66

JOHCE OF MICHAEL SATE OF MICHIGA GLENN E. RICHARD No. 13040 GRONAT & RESIDE

v	$\mathcal{A}$	The same of the sa
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Klery C. Le Loy Date	September 9, 1997
216 0010-		

Signed by\_ Glenn E. Richard Date *C/CT*, 19, 1997

Surveyor's Michigan License No. 13040