PAGE 164

Filed under Remonumentation Act 345 of 1990

MAY 1 8 1997

Maria Carant

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Street of the street was

STATE OF MICHIGAN LENAVEE COUNTY Filed

Lenawee	Located In:	Corner Code #		20 DEC 96	10:54 A.X.
(County) 1. Public Land Survey	T <u>-8-S</u> R <u>-3-E</u>	<u>M-6</u>			E D. KNOX R OF DEEDS
Property Controlling S in Section S Miscellaneous S	T R		Register o	f Deeds Starr	np & File Number
Property in Sec S	TR		A B	CDEF	GHIJKLM
4. Lot No Recorded	d Plat		2 -	- 5 4	
5. Private Claims			3 4 7 5	8 9	10 11 12
ı, <u>Glenn E. Richard</u>	, in a field	l survey on <u>September 9</u> 19	96_, 6 -18	8 17 16	15 14 13
do hereby certify that under requirem in lines 1 and 2 above were in confi current manual of survey instructions	formance with regulation of the United States De	ns and rules therefore as require epartment of the Interior, Bureau	ed in the 8 19 of Land	9 20 21	22 23 24
Management or by a decree of a Cour above were in conformance with the Court of Law; established, re-es expressed below:	rules of the Michigan Bo	oard of Land Surveyors or by a De	cree of a 10 30	29 28 1 32 33	27 26 25 34 35 36
NOTE: Not more than 4 corners on this certificate.	, all in the same town	n and range, may be recorded	13 🗀		

Description of original monument and accessories and/or subsequent restoration:

*NOTE: SEE COMMENTS & SKETCH ON BACK

G.L.O. 1824, John Mullett ran a corrected town line from the South and set 1/4 Sec. post 4.52 chains North of the old 1/4 Section corner.

Could not find any records of anyone ever finding this corner.

May 22, 1972, K.L. Suydam re-established the corner on line and midway between the NE. and SE. corners of Sec. 13, T8S-R3E, and recorded it in L. 1, P. 471 and recorded a survey in L. 1 of Surveys, P. 274, which shows the corner.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.

September 4, 1996, I dug and found a 1/2" iron pipe as recorded by K.L. Suydam. September 9, 1996, I found the 1/2" iron pipe under the first course of asphalt, I replaced it with a 3/4" X 3' gas pipe capped G.E.R. 13040 and set monument box with top 1 3/4" above the pavement to be level with the top course of asphalt being laid by the Lenawee County Road Commission.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' gas pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. "X" cut on bolt in end of C.M.P. N 35° W 39.88

Fd. "X" cut on bolt in end of C.M.P. N 30° E 58.44

Fd. nail & disc in post next to Tel. pedestal N 65° E 34.94

Fd. dbl. hd. nail & disc in Elec. pole S 5° W 285.85

Fd. dbl. hd. nail & disc in Elec. pole \$ 5° E 324.87

3/4" X 3' gas pipe in monument box at A-6, T8S-R4E South 236.40

BYONAL SUP

Ratified by Peer Group in accordance with P.A. 345

Glenn E. Richard

Surveyor's Michigan License No. _13040

TE MICHICALO

SATE OF MICHIGA

GLENN E

RICHARD No. 13040 COMMENTS: The G.L.O. Plat maps for T8S-R3E and T8S-R4E are in conflict as to the jogs of the section lines.

1819, Joseph Wampler surveyed the township line from North to South, apparently making an error of approximately 5 chains as he shows the last distance to be 96.15 chains and corrected all temporary corners 16.15 chains South.

1824, John Mullett re-surveyed and corrected this line surveying from South to North, calling out old corners and setting new corners at 40 chain intervals and shows the last distance as 90.28 chains for a difference of 5.87 chains. James Blair's 1880± records of each section show the jogs to be to the corrected corners set by John Mullett. The current occupation of roads and the present monumentation of corners and the measurement of the east line of township fit reasonably well with John Mullett re-survey of the line.

