## Filed under Remonumentation Act 345 of 1990 LAND CORNER RECORDATION CERTIFICATE IBER 1 PAGE 167

	Filing Re	quirement of Act 74, Mich.	P.A. 1970	
For corners in	Located In:	Corner Code #		STATE OF MICHIGAN LENAVEE COUNTY FILED
Lenawee (County)	Located In:	Comer Code #		LITCA
1. Public Land Survey	T <u>-8-S</u> R <u>-4-E</u> TR TR	A-6		20 DEC 96 10:56 A.M. JEANETTE D. KNOX REGISTER OF DEEDS
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec</li> </ol>	TR STR STR STR			eds Stamp & File Number
	•		A B C	DEFGHIJKLM
4. Lot No, 5. Private Claims	Recorded Plat		2 6 3 4 7 5 5 5 5 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6	5     4     3     2     1       8     9     10     11     12
ı. Glenn E. Richard	, in a fi	eld survey on <u>September 9</u>	19 966 <del>  1</del> 8	47 46 15 14 13
do hereby certify that under in lines 1 and 2 above we current manual of survey in Management or by a decree above were in conformance	requirements of P.A. 74, Michigere in conformance with regulate structions of the United States of a Court of Law and/or that the with the rules of the Michigan	gan P.A. of 1970, the corner points milions and rules therefore as required. Department of the Interior, Bureau he corner points mentioned in lines 3 Board of Land Surveyors or by a Deed, re-monumented, recovered, for	entioned 7 ed in the 8 of Land , 4 and 5 ecree of a 10 ound as 11	20 21 22 23 24 29 28 27 26 25 32 33 34 35 36
		wn and range, may be recorded	13	<u> </u>
on this certifica				
A. Description of original monument and accessories and/or subsequent restoration:				
*NOTE: SEE COMMENTS & SKETCH ON BACK				
1883, James Bl Section 18. J.L. Richard re July 1973. We	lair re-established this co cord is a copy of J. Blair dug but didn't find any t recorded it in L.2, P. 485.	oy the original government: rner "Brick, iron & stone" mi race of the corner. Set a 3/4 . (Set corner in line of fence	dway between the " x 24" iron pipe in	line with fence East and on
B. Description of corr	ner evidence found and/or m	nethod applied in restoring or re	establishing corner:	
capped G.E.R. September 9.	13040 from the two rem	nt had been scarified and the aining witnesses from L.2, P. e under the first course of a che top course of asphalt bei	485 and on line be sphalt and set mor	tween M-5 & M-7, T8S-R3E. nument box with top 1 3/4"
C. Description of mor	nument for corner and acce	ssories established to perpetuat	e locating the positio	n of the corner:
•		1. <i>计设施的</i> 数据数据分表的。		
evidence of the Fd. "X" on to Fd. "X" on to Fd. dbl. hd. r Fd. dbl. hd. r NW. corner S	the capped G.E.R. 13040 in the position of the corner p of bolt on end of C.M.P p of bolt on end of C.M.P nail & disc in Elec. pole S tection 18, North 2625.13 ection 18, South 2622.42	2. N:5° W 270,47 2. N 5° E:289.01 15° E 90.52 25° W 53.43	epteu as the best a	GLENN E. RICHARD No. 13040
Ratified by Peer Group i	n accordance with P.A. 345	5 Co. Rep Hen Chicka	Date <u>12-16-</u> 1	19
Signed by & Burn	Filail Da	10 00		THE PERSON NAMED IN COLUMN
	E. Richard		FORM APPROVED BY MICHIG	AN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
San voyor o misnigan als			·	REVISED MAY 14, 1975

comments: The G.L.O. Plat maps for T8S-R3E and T8S-R4E are in conflict as to the jogs of the section lines.

1819, Joseph Wampler surveyed the township line from North to South, apparently making an error of approximately 5 chains as he shows the last distance to be 96.15 chains and corrected all temporary corners 16.15 chains South.

1824, John Mullett re-surveyed and corrected this line surveying from South to North, calling out old corners and setting new corners at 40 chain intervals and shows the last distance as 90.28 chains for a difference of 5.87 chains. James Blair's 1880± records of each section show the jogs to be to the corrected corners set by John Mullett. The current occupation of roads and the present monumentation of corners and the measurement of the east line of township fit reasonably well with John Mullett re-survey of the line.

