OCT 1 9 1998

Filed under Remonumentation Act 345 of 1990 IBER 1 PAGE 266

SECTION

Property in Sec

5. Private Claims

expressed below:

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN LENAWEE COUNTY FILED

ABCDEFGHIJKLM

	Filing Requirement of Act 74, Mich. P.A. 197

For corners in 15 SEP 1998 8:59:11 AM Lenawee Located in: Corner Code # VICTORIA J. DANIELS REGISTER OF DEEDS 1. Public Land Survey T-8-S R-4-E R 2. Property Controlling S R in Section Miscellaneous R Register of Deeds Stamp & File Number

I, Glenn E. Richard	, in a field survey on	April	10.	19_	98	
do hereby certify that under requirements of P.A. 74	Michigan P.A. of 1970.1	he com	er poir	its m	ention	ed
in lines 1 and 2 above were in conformance with i	regulations and rules th	erefore	as re	quire	d in t	he
current imanual of survey instructions of the United 3	States Department of th	e Interio	r, Bur	eau	of Lai	nd
Management or by a decree of a Court of Law and/or	that the corner points m	entioned	l in line	es 3.	4 and	15
shove word in conformance with the rules of the Min						

3 4 5 6 7 8 9 Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 8 11

1

2

12

13

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Wampler set post cor Sec. 12 & 13 Beech 6 S 18 W 22 Hickory 5 N 19 W 11

1891 James Blair found stake and tile

, Recorded Plat

1928 Harold Clegg RLS 13578 found gas pipe & tile while surveying Thompson Hwy.

1977 I dug through the pavement and found gas pipe and bricks & replaced the gas pipe with a 1" X 4' iron pipe and I recorded it in L 4, P 43

1980± Lenawee Co. Road Commission rebuilt the road and set a monument box at the iron pipe

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

April 10, 1998 Found iron pipe in monument box. I drove the re-rod in and pulled it out and it had trace of bricks or tile on it. Replaced the iron pipe with 5/8" X 3' re-rod with a Lenawee Co. Re-mon cap stamped P.S. 13040.

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

5/8" X 3' re-rod in monument box with a Lenawee Co. Re-mon cap stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Found "X" cut on N. end C.M.P. S 65° W 20.85 Found "X" cut on S. end C.M.P. S 15° W 87.96 Found "X" cut on W. end C.M.P. S 5° W 120.71 Found "X" cut on E. end C.M.P. S 15° W 127.85 Fd dbl hd nail & disc in E.P. S 40° E 45.67

A-7 T8S R5E South 124.74 GLO =1.89 links =124.74' M-6 T8S R4E North 2554.19



Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Blann & Refail Date June 9, 1998
Signed by Glenne Ruchard D.	ate Aug 23, 1998_
Glenn E. Richard	-
Surveyor's Michigan License No. 13040	FORM APPROVED BY MICHIGAN STATE BOARD OF I