OCT 1 9 1998

Filed under Remonumentation Act 345 of 1996 IRER 1 PAGE 263

SECTION

LAND CORNER RECORDATION CERTIFICATEL

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN LENAVEE COUNTY FILED

| For corners in | | | |
|--|---|---|--|
| Lenawee | Located in: | Corner Code # | 15 SEP 1998 9:02:51 AM |
| 1. Public Land Survey | T <u>-9-S</u> R <u>-4-E</u> T R T R | M-2 | VICTORIA J. DANIELS REGISTER OF DEEDS |
| in Section | S T R S T R S T R R S T R R R S T R R R R | | Register of Deeds Stamp & File Number |
| 4. Lot No, Rec 5. Private Claims | corded Plat | | A B C D E F G H I J K L M |
| I, Glenn E. Richard , in a field survey on July 13, 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: | | | 5 6 18 17 6 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 |
| NOTE: Not more than 4 on this certificate | | and range, may be recorded | 11 12 31 32 33 34 35 36 13 |
| A. Description of original | I monument and accessories a | nd/or subsequent restoration: | |
| 1887 James Bla | air found stone (Survey of Se | st Sugar 16 N 60 W 5 Beech ection 6 T9S R5E) | 11 N 30 E 6 |

NOTE: The distances north on Blair's 1887 and 1890 survey appear to be to a common corner but he didn't make any mention of it on the surveys.

1904 John Hettinger, Fulton Co. Surveyor surveyed S 1/2 Sec. 1. The notes call for stone

1916 Ohio-Michigan Report of State line survey "The General Land Office measurements with error prorated was adopted as the stone corner of Sections 1 and 6

1945 Lucas County Ohio Engineer's office records call for stone

1980 Kenneth Suydam RLS 17636 found pointed stone and set 1/2" X 36" iron pipe over stone and recorded it in L4 P318 for A-2 T9S R5E

1980± Lenawee County Road Commission rebuilt the road and set a monument box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 13, 1998 Found iron pipe in monument box with top bent over stone I tried to drill a hole in the top of stone but the top broke off. Set 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 with top over the stone. The peer group reviewed the records pertaining to this corner and M-2 T9S R5E and approved them as a common corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in a monument box and is accepted as the best available evidence of the position of the original corner

dbl. hd. nail and re-mon tag in E.P. N 40° W 252.43 dbl. hd. nail and re-mon tag in E.P. S 40° W 266.30 Drill hole in top of state line post #46 S 2º W 828.98 Bolt with "X" cut on top in monument box at state line South 828.33 Steel fence post N 80° E 18.34 The corner is 5.4 East of pavement centerline

SATE OF MICHIO GLENN E. RICHARD No. 13040 BONAL SUP WATER THE TANK

| | Q1 a11 | | · | "II |
|--|-------------------------|---------|---------------|-----|
| Ratified by Peer Group in accordance with P.A. 345 | Co. Rep Glenne trickard | _Date _ | July 21, 1998 | |
| Signed by Shan & Poland Da | ate Aug. 23 (900 | | | |

Glenn E. Richard Surveyor's Michigan License No. 13040

REVISED MAY 14, 1975

REVISED JAN., 1983