LAND CORNER RECORDATION CERTIFICATE

For corners in							
	Located In:	Corner Code #					
(County)	cocated iii.	comer code #					
Dublic Land Company	T 450 D 60	. •					
Public Land Survey	T <u>45N</u> R 8W						
	TR						
	1R						
Description Control III	S TR						
Property Controlling	S R						
Section	S I R					5	
Miscellaneous	<u> </u>			Register Number	of Deeds	Stamp	& File
Property in Sec.	S TR						
Lot No Dos	anded Diet		1 A B	CDE	FG	H I	J K L 1
Lot No, Rec Private Claims	orded Plat		2 - 6	!	_		
rivate Claims			3				i Ti
	Jun 19	2003			ŢŢ,		
Stephan J. Szyszkoski	, in a field survey on	. 20 do hereby	state -	777		ľ	1 <u>11</u> 2
at under requirements of P.A.	. 74, Michigan P.A. of 1970, the c	orner points mentioned in lines 1	and 2			 	
ove were in conformance wi	th regulations and rules therefore	e as required in the current man	ual of 6 1 9	╼┼╾┇┸╌┼	-161	5	1413
vey instructions of the Unite	d States Department of the Interio	or, Bureau of Land Management of	rbya 7	- - - 		╀┷┼	
formance with the rules of	or that the corner points mention the Michigan Board of Land Surve	oned in lines 3, 4 and 5 above we wors or by a Decree of a Court of	ere in 819		_21	22	2324
ablished, re-established, mo	numented, recovered, found as ex	xpressed below:	رست،				
			, ,				
	corners, all in the same town	and range, may be recorded	1 10 30	1-29-1	28	17	2 6 25
on this certificate.			11			1-1-	
.			12 31	32	_3'3;	34	35 36-
Description of original r	nonument and accessories and	d/or subsequent restoration:	13			Щ.	
			Life to the second of the seco				
Description of corner e The original post and a nd. Reestablished the co rded by Buckler in 1961 a	vidence found and/or method ccessories were not recovered orner midway and on a line of and Neff in 1968), and reesta	. Found no acceptable evide mean true bearing between M blished K7 (monumented in 19	nce of the pos 7 (remonumente	ition of t d in 1960	by Billy	D. Ruc	kler and
Description of corner e The original post and a nd. Reestablished the co rded by Buckler in 1961 a	vidence found and/or method ccessories were not recovered orner midway and on a line of	. Found no acceptable evide mean true bearing between M blished K7 (monumented in 19	nce of the pos 7 (remonumente	ition of t d in 1960	by Billy	D. Ruc	kler and
Description of corner e The original post and and Ind. Reestablished the corded by Buckler in 1961 a ing and distance of this Description of monumen Set a 1"IDx36" I.pipe wi MDNR cap, appropriately ed, scribed, and set meas Spruce S45M 6.6' "1; Balsam S36E 11.55'	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4"	1. Found no acceptable evider mean true bearing between M blished K7 (monumented in 19 5289.78' (80.15 ch).	tine the positive positive to positive the positive posit	ition of d in 1960 Buckler).	by Billy . I obser	D. Ruc	kler and
Description of corner e The original post and an Ind. Reestablished the corded by Buckler in 1961 a Ing and distance of this Description of monumen Set a 1"IDx36" I.pipe wi I. MDNR cap, appropriately ed, scribed, and set meas Spruce S45W 6.6' "1, Balsam S36E 11.55' aple N84W 3.9'	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, the for corner and accessories e ith a 4" y stamped. 3. nails in: /48 NBT"	1. Found no acceptable evider mean true bearing between M blished K7 (monumented in 19 5289.78' (80.15 ch).	tine to postile STEPHAN SZYSZKO LAND	ition of the control	by Billy . I obser	D. Ruc	kler and
Description of corner e The original post and an Ind. Reestablished the corded by Buckler in 1961 a Ing and distance of this Description of monumen Set a 1"IDX36" I.pipe with MDNR cap, appropriately ed, scribed, and set meas Spruce S45M 6.6' "1, Balsam S36E 11.55' aple N84M 3.9' aple S68E 38.7'	vidence found and/or method ocessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, the for corner and accessories eith a 4" y stamped. 3. nails in: /4S NBT" do do do	1. Found no acceptable evider mean true bearing between M blished K7 (monumented in 19 5289.78' (80.15 ch).	ring the position of the posit	ition of the of	by Billy . I obser	D. Ruc	kler and
Description of corner e The original post and an Ind. Reestablished the corner rded by Buckler in 1961 a ing and distance of this Description of monumen Set a 1"IDx36" I,pipe with MDNR cap, appropriately ed, scribed, and set meas Spruce S45M 6.6' "1, Balsam S36E 11.55' aple N84M 3.9' aple S68E 38.7' ed a squared cedar post a	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent.	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	tine to postile STEPHAN SZYSZKO LAND	ition of the control	by Billy . I obser	D. Ruc	kler and
Description of corner e The original post and and. Reestablished the corned by Buckler in 1961 at a more and distance of this ing and distance of this set a 1"IDx36" I.pipe with the corner and set meas spruce \$45% 6.6' "1, Balsam \$36E 11.55' aple N84% 3.9' aple \$68E 38.7' ed a squared cedar post a ings are magnetic. Distance of the corner and the co	vidence found and/or method ocessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent. ances are	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	strephan SZYSZKO LAND SURVEYO	ition of the of	by Billy . I obser	D. Ruc	kler and
Description of corner e The original post and and. Reestablished the corned by Buckler in 1961 at a more and distance of this ing and distance of this set a 1"IDx36" I.pipe with the corner and set meas spruce \$45% 6.6' "1, Balsam \$36E 11.55' aple N84% 3.9' aple \$68E 38.7' ed a squared cedar post a ings are magnetic. Distance of the corner and the co	vidence found and/or method ocessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent. ances are	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	strephan SZYSZKO LAND SURVEYO	ition of the of	by Billy . I obser	D. Ruc	kler and
Description of corner end of the original post and and and. Reestablished the coorded by Buckler in 1961 and and distance of this ing and distance of this end of the set a 1"IDx36" I,pipe with the set a 1"IDx36" I,pip	vidence found and/or method ocessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent. ances are	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	strephan SZYSZKO LAND SURVEYO	ition of the of	by Billy . I obser	D. Ruc	kler and
The original post and and and. Reestablished the coorded by Buckler in 1961 aring and distance of this Description of monument Set a 1"IDx36" I.pipe with MDNR cap, appropriately ted, scribed, and set measured.	vidence found and/or method ocessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent. ances are	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	strephan SZYSZKO LAND SURVEYO	ition of the din 1960 Buckler).	by Billy I obser	D. Buc	kler and
Description of corner end the original post and and and. Reestablished the coorded by Buckler in 1961 aring and distance of this ing and distance of this between the content of the corner of the cor	vidence found and/or method ocessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent. ances are	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	stephan Szyszko, LAND SURVEY(ition of the din 1960 Buckler).	by Billy I obser	D. Buc	kler and
Description of corner e The original post and an Ind. Reestablished the corded by Buckler in 1961 a ing and distance of this Description of monumen Set a 1"IDx36" I.pipe wi MDNR cap, appropriately ed, scribed, and set meas Spruce S45M 6.6' "1, Balsam S36E 11.55' aple N84M 3.9' aple S68E 38.7' ed a squared cedar post a ings are magnetic. Dista	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent. ances are tag 33986.	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	strephan SZYSZKO LAND SURVEYO	ition of the din 1960 Buckler).	by Billy . I obser	D. Buc	kler and
Description of corner e The original post and an Ind. Reestablished the corded by Buckler in 1961 a ing and distance of this Description of monumen Set a 1"IDx36" I,pipe with MDNR cap, appropriately ed, scribed, and set meas Spruce S45M 6.6' "1, Balsam S36E 11.55' aple N84M 3.9' aple S68E 38.7' ed a squared cedar post a ings are magnetic. Dista	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4S NBT" do do do adjacent. ances are tag 33986.	mean true bearing between Miblished K7 (monumented in 195289.78' (80.15 ch).	stephan Szyszko, LAND SURVEY(ition of the din 1960 Buckler).	by Billy I obser	D. Buc	kler and
Description of corner e The original post and an Ind. Reestablished the corded by Buckler in 1961 a ing and distance of this Description of monumen Set a 1"IDx36" I.pipe wi MDNR cap, appropriately ed, scribed, and set meas Spruce S45M 6.6' "1, Balsam S36E 11.55' aple N84M 3.9' aple S68E 38.7' ed a squared cedar post a ings are magnetic. Dista	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4\$ NBT" do do do adjacent. ances are tag 33986.	Found no acceptable evided mean true bearing between Mishlished K7 (monumented in 195289.78' (80.15 ch).	stephan SZYSZKO: LAND SURVEY(No. 33986	ition of d in 1960 Buckler)	by Billy I obser	D. Buc	kler and
Description of corner e The original post and and. Reestablished the corded by Buckler in 1961 aing and distance of this Description of monument Set a 1"IDx36" I.pipe with MDNR cap, appropriately ed, scribed, and set meas Spruce S45M 6.6' "1, Balsam S36E 11.55' aple N84M 3.9' aple S68E 38.7' ed a squared cedar post aings are magnetic. Distance and to nail with the sened by	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4\$ NBT" do do do adjacent. ances are tag 33986.	Found no acceptable evider mean true bearing between Mishlished K7 (monumented in 195289.78' (80.15 ch).	stephan SZYSZKO: LAND SURVEY(No. 33986	ition of the d in 1960 Buckler). SKI Facilities	by Billy I obser	D. Buc	kler and B mean true
Description of corner end. Reestablished the counted by Buckler in 1961 at ing and distance of this ing and distance of this. Description of monuments at a 1"IDx36" I.pipe with the control of the cont	vidence found and/or method occessories were not recovered orner midway and on a line of and Neff in 1968), and reesta line to be S89 deg. 29'03"W, t for corner and accessories e ith a 4" y stamped. s. nails in: /4\$ NBT" do do do adjacent. ances are tag 33986.	Found no acceptable evider mean true bearing between Mishlished K7 (monumented in 195289.78' (80.15 ch).	sting the position of the posi	ition of the d in 1960 Buckler). SKI Facilities	by Billy I obser	D. Buc	kler and B mean true