1993 LUCE COUNTY REMONUMENTATION CORNER

COMMISSION

C problema C

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	· ·····g ·····quii	small of Flot 14, mion	· · · · · · · · · · · · · · · · · · ·	
Luce	Located In:	Corner Code ##		0 02
(County)			filed da -de	2 A.D., 19 <u>93</u>
1. Public Land Survey	745N R 9W	B-13 Corner	At 10:00 Liber 2 Flie No. Pa	o'clock A.M.
	T R		Flie No. Za	469 X
	T R		Janath!	1. Makar
2. Property Controlling	S T R		Luca Correta	Reg. of Deeds
in Section	S R		Luce Edunit	A IVOR. OI Deeca
3. Miscellaneous	S T R		Register of D	leeds Stamp & File Number
Property in Sec.	S T R		negister of b	reeus Stamp & File Humber
	lecorded Plat		A B	CDEFGHIJKEM
5. Private Claims				
			3	-
			<u> </u>	
, Keith R. Waters	in a field survey onNove	ember , 19 <u>93</u>	·	
do hereby certify that under rec	, in a field survey on tuirements of P.A. 74, Michigan P.A.	of 1970, the corner points mar	Nionad 5	┞╸┠┈╏┈╏┈╏┈╏┈╏┈
in lines 1 and 2 above were in	conformance with regulations ar	d rules therefore as required	in the	
	uctions of the United States Depar			
Management or by a decree of a	a Court of Law and/or that the corne	r points mentioned in lines 3,	4 and 5	20 21 22 23 24
above were in conformance wit	in the rules of the Michigan Board (of Land Surveyors or by a Dec	ree of a	1 1 1 1 1 1
	e-established, monumented, re-	monumented, recovered, for	and as	
expressed below:			10 -30-	29 28 27 26 25
NOTE: Not more than 4 co	orners, all in the same town a	nd range, may be recorde	d 11	╃═╀┈╀═╀┈┞═╃┈┼═┼═┼
on this certificate.		- '	123	32 33 34 35 36
·			13	
 A. Description of original r 	monument and accessories and	d/or subsequent restoration	on:	
B-1 (T45N, R9W)) 1/4 Corner Commo	n to Sec. 6, T45	N, R9W & Sec	c. 31, T46N, R9W
				ATTEN A
Original ties t				OF MICHON
Beech 8, N44°E	34 links			Take
Beech 7, N45°W	19 links			A STATUE
·				KEITH R.
				* WATERS *
				SURVEYOR *
				No.
P. Description of corner of	uidanan faund and/or mathad	noolinal in vootoving as year		33142
b. Description of comer e	vidence found and/or method	applied in restoring or rees	stablishing corner;	SED TANK SURFIE
B-1 (T45N, R9W)			LAND
This corner is	being re-establis	hed as part of t	the Luce Cou	nty Remonumentation
Program. Found	d no evidence of c	orner. Re-estal	olished corn	er 33 feet north of
a corner fence	post on the south	side of east-we	est dirt road	d (County Road
440) on extens	ion of fence line	to south. Dista	ance to Sect	ion corner west is
2596.00' (2592	.48' G.L.O.) and d	istance to Sect [.]	ion corner e	ast is 2666.65'
(2640' G.L.O.)	. Corner is 22.80	' north of a sta	raight line	between said
Section corner	s. North-south po	sition fits well	l with remain	ns of right-of-way
fences 33 feet	north and south o	f section lines	hoth east a	nd west of 1/4
corner.		. 2002/01. 111105	Doen case a	nd west of 1/4
C. Description of monume	nt for corner and accessories	established to perpetuate	locating the position	of the corner:
B-1 (T45N, R9W)			•	
Corner is a 11	L		_4	
nonth of the	rebar with 3½" al	uminum Luce Cou	nty cap appr	oximately 3 feet
line to the co	enterline of east-	west dirt road	(County Road	440) at a fence
Tine to the So	uth. Witnesses:			
51 Sugan Man	le, S39°E 49.86'	Note: Diete:		
All Cuman Map	16 000 E 40.00	mute: utstance	es are to a	nail and tag in the
- Suyar Map	le, \$67°W 32.76'	Side of tree.	irees are b	lazed and painted.
	3°E 13.93'	bearings are co	ompass beari	ngs corrected for
o" Ked Maple	, \$73°E 53.04'	declination.		
	•			
1/41 0	· \-			
Signed by <u>Keitt</u> R	. Walen	Date	(2-20-9)	<u> </u>
Surveyor's Michigan Licens	e No33142			