LUCE COUNTY REMONUMENTATION CORNER

APR 0 1 1996

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970

For corners in COMMISSION	1970
Luce Located In: Corner Code #	LUCE COUNTY REGISTER OF DEEDS
1. Public Land Survey T45N R 10W K-4 T R T R T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	Recorded 02-29-1996 15:21:30 Lbcr 2 Pay(652 Kathy S. Mahar, Resister REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	1 A B C D E F G H I J K L M
	2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
Keith R. Waters , in a field survey on 12/18 , 19 do hereby state that un	3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of	in _
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	/or 6 18 17 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monument	sd, /
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25
,	11
	12 31 32 33 34 35 36
1850 - Original ties to set post: Beech 5, S62°E 20 links - Beech 8, S72°W 17 links. 1990 - Neil E. Hill, P.S. 27447, page 434, Luce County recorded corners. Set a 1/2" iron with cap #27447 in a monument box. Location established by retracement of a DNR survey by Billy Buckler, RLS 8887 (DNR survey is recorded in page 1, Luce County recorded surveys). North-south position of corner appears to be in close agreement with DNR survey. East-west position was determined by a straight line between Section corners north and south. Witnesses: Guy Pole, S50°E 35.29' - 8" Red Pine, N60°E 69.74" 30" Maple, S85°W 83.07' - 25" Maple, S55°W 98.07' - PK nail/tag, WEST 10.40' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: This corner is being perpetuated as part of the Luce County Remonumentation Program. Found a 1/2" iron pin with cap #27447 in a monument box 10.4 feet east of the centerline of Highway M-123, on the approximate extension of an old fence line to the west. Also found witness objects as called for in 1990 LCRC, could not find a measuring rail in the 30" maple. Corner is on line between Section corners north and south, and is 13.25 feet north of a split between said Section corners. The north-south position appears to be in close agreement with above mentioned DNR survey. The east-west position is in conflict with the DNR survey, which assumed the corner location as being in the centerline of the road. No evidence appears to exist which would indicate the center of the road being the section line, other corners to the north along M-123 are also east of centerline.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 1/2" iron with cap #27447 in a monument box 10.4 feet east of the centerline of M-123, opposite an old fence line to the west and a gravel drive to the east. Witnesses: Nail/tag P.S. 33142 in power pole (ML4/47), WEST 52.97' Nail/MDOT tag in 8" Red Pine, N60°E 69.74' Nail/MDOT tag in guy pole, S43°E 35.29' Nail/MDOT tag in center of Highway M-123, WEST 10.40' Note: Bearings are compass bearings corrected for declination. Date 12-29-95 LAND Signed by Land Date 12-29-95	
	C-C7-43 WAND
Surveyor's Michigan License No. 33142	•