LAND CORNER RECORDATION CERTIFICATE A 1970

	Filing Requirement of Act 74, Mich. P.				
For corners in					
Luce	Located In:	Comer Code #			
(County)					
1. Public Land Survey	Ť F	₹ <u>11#</u> <u></u> ₹			
Property Controlling in Section Miscellaneous Property in Sec.	S TF S TF				
4. Lot No, Reco	orded Plat				

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat	
5. Private Claims		-

Oct 12 1998

I<u>Stephan J. Szyszkoski</u> _, in a field survey on . 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

. 4	<u> </u>	В (: I)]	EI	F C	; H		Ι,	J	()	
1	Γ										Ι	
2	<u> </u>	6	 -	5—	-	<u> </u>	⊢;	<u> </u>	 - :	2	 	<u>i —</u>
3	_	_			lacksquare							<u> </u>
4	Ļ.	ļ_	L.,	¦ ⊪—	L	ا 9	1	0	<u>_</u> 1	1	Ļ,	
5	L	<u> </u>		$oxed{oxed}$				L	ļ	_	_	<u> </u>
6	L,	 .e—	L_,	_	_1		1	 5—	_,	<u>ا</u>	L_1	ا 3—
7	Ľ	Ľ				Ĺ		Ĺ		Ĺ	L	Ĺ
8		 و	,	٥	,	Í	,	[,		١,	
	Ľ	,— 	ı,	ĭ	_	Ţ	_'	<u> </u>	<u>_</u>	ĭ	T-~	1 1
9		\vdash	—	-	-	_	_	_			\vdash	\vdash
10	3	ļo—	— 2	9_	<u> </u>	8—	<u>2</u>	' 7—	-2	6-	-2	<u>'</u> 5—
11	_	_	_	_	L	L	_	_			L.,	<u> </u>
12	L,	<u> </u>	_,		_,	_	_3	_	L3	5—	L,	 6
		i		Ī						Ľ	[]	ĺ
13	_			_		_	-		_	_		_

A. Description of original monument and accessories and/or subsequent restoration:

(JI3) Quarter corner common to Section 2 T44M-R11M and Section 35 T45M-R11M. Corner established in 1841 by John Burt: "Mest on south side of Section 35 (T45N-R11W)...40.00 Set or section post Beech 14 MSE 37, do 10 M27W 58 ... 80.00 set post corner sections 34 & 35°. Corner reestablished in 1967 by Billy D. Buckler, RLS: 'This corner re-established on line bet. two corners and at record distance (40.00 chs) from west Sec. Cor. No evidence of original cor. Corner monument 1" pipe with 4" aluminum cap. Mitnesses to corner; 8" H. Maple (1/45 MBT) M75E 17.6', 10" H. Maple (1/45 MBT) 536E 21.2'". I found nothing in the available second at the Michigan Dept. of Natural Resources Newberry District Office which explains why Buckler chose this method of reestablishing the corner and can only conclude that it is not documented. I also note that it is unclear which corners are indicated by Buckler's statement "on line bet. two corners". It is likely that II was used on the west but highly unlikely that XI was used on the east as Buckler susequently reestablished K1 by proportionate methods using J1 for control. Suckler's latitudinal control for J1 was probably I1 and M1.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(JI3) Recovered the 1967 monument as described, a 1° I.O. iron pipe capped with a 4° dia. cast aluminum MDMR tablet, appropriately stamped, in good condition, and at record bearing from the two 1967 witness maples, both recovered in good condition with upper and lower blazes overgrown. I note that the 1967 record is in error in that the distances to the MBTs appear to have been transposed. The 8" H. Maple (now 12") was found at 21.2', and the 10" H. Maple (now 18") was found at 17.6'. The monument was recovered 2631.06' mast of II and 10.3' north of a straight line between II and Mi. During the course of my survey, I removed the monument and later reinstalled it in the position at which I found it, being the 1967 position herein recorded. I accept the monument as a careful and faithful reestablishment of the position of the original corner. I found the distance from \$11\$ to Suckler's monument to the east at \$1 to be 2666.12' and from K1 to Buckler's monument at #1 to be 5323.22'. I made new markings on the 1967 witness trees and marked two new bearing trees as described below. Corner recovered and rewitnessed by T.Stark and M.Feldpausch, Newberry District Office.

nd accessories established to perpetuate locating the position of the corner.

C. Description of monoment for content and
(J13) Set 1 ID x36 iron pipe with 4.
aluminum MDMR cap. Blazed, scribed, and
set measuring nails in:
18" Maple \$37E 17.65" "1/45" (1967 wit) 🐉
18" Maple S37E 17.65' "1/45" (1967 wit) 12" Maple N76E 21.3' "1/45" (1967 wit)
8" Maple N40N 5.3' "1/4S NRT"
6" Maple SO4N 8.55' "1/4S NBT"
Placed a 4" squared and scribed cedar
post adjacent. Bearings are magnetic.
Distances are horizontal.

STEPHAN J SZYSZKOSKI LAND SURVEYOR

For the Michigan Department of Matural Resources - Forest Management Division