



1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in										
Luce		Located In:	Corner Code ##		_						
	(County)	Loodica III.	Comer Code 44	Filed_/a			•				
1.	Public Land Survey	T <u>45N</u> R <u>11W</u> T R T R		File No.	oo iba	_0'0	lock/	9 . H	l. -//		
	Property Controlling in Section Miscellaneous Property in Sec.			Luce C	•	•	••			ber	
5.	Private Claims	Recorded Plat		2 3	B	C D 5-	E F	G H	1 J		L M
do in cui Ma abe Co	hereby certify that under re- lines 1 and 2 above were in rrent manual of survey instrangement or by a decree of ove were in conformance wi	quirements of P.A. 74, Michigan P.A n conformance with regulations ar actions of the United States Departs a Court of Law and/or that the corneith the rules of the Michigan Board re-established, monumented, re-	of 1970, the corner points ment nd rules therefore as required i tment of the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decre	ioned 6 in the 7 Land 7 and 5 8 ee of a	18 19 30	20-29-	21-	22-27-27-	23		-24
NC	OTE: Not more than 4 or on this certificate.	corners, all in the same town a	nd range, may be recorded	11 12 13		32	33-	34	35-		-36
A.	(D-13) South 1/4	monument and accessories an Corner Section 32, T4 (Township Line and Co	5N-R11W and North 1		Sect	ion	5,				

1841: Corner established by John Burt for William A. Burt

Champion International Notes:

04/22/1976:

Calls for post

10/19/1978:

Calls for scribed post

Undated:

Calls for post set 14 1/2 links North of corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner reestablished as part of the Luce County Remonumentation Program. Found a rotted off wood post with a 4" square wood post on North side. Found a wood corner fence post - the intersection of the East right-of-way fence for the road to the North and a fence to the East. (Note: Road curves in area of corner - corner not in road). Approximately 500' North of the corner the right-of-way fences are 50' apart. Did not hold rotted off wood post for corner position. Reestablished corner position 25.0' West of the corner fence post on the extension of the fence line to the East. Wood post bears N24°W 9.8' from reestablished corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 1/2" x 24" iron with a 3 1/4" diameter stamped aluminum cap, 6" below surface. Falls on Northeasterly edge of two track woods road (bears S65°E). Falls on extension of fence line to East (25' West of corner post). Falls on approximate extension of centerline Luce County Road 473 to North and West (road curves, gravel).

14" Spruce	N48°E	36.00'
10" Cedar of Twin	S36°E	39.38'
6" Yellow Birch	S04°W	40.46'
9" Cedar of Triple	S32°W	40.84'

Signed by Williams No. 27450

Date 12 16 93

No. 27450 CALON END SI

MILLIAM

KAR**R** Land Surveyor

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination. Distances

REVISED MAY 14, 1975

are to a nail with P.S. 27450 tag in side of witness objects unless noted.

REVISED JAN., 1983