Luce County Remonumentation Program

				1993
Fav commun la		ER RECORDATION CERT ement of Act 74, Mich. P		VISSION
For corners in				
Luce (County)	Located In:	Corner Code ##	Med 62-22 A.D	
Public Land Survey	T 45N R 12W T	G-7	File No. Page	* <u>A</u>
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S S T R S T R R R R R R R R R R R R		Luce County Reg.	
	ecorded Plat		A B C D E I	F G H I J K L M
in lines 1 and 2 above were In current manual of survey instruct Management or by a decree of a above were in conformance with Court of Law; established, re expressed below: NOTE: Not more than 4 co on this certificate. A. Description of original materials (G-7) Section Corn	in a field survey on Novembrairements of P.A. 74, Michigan P.A. conformance with regulations and citions of the United States Depart Court of Law and/or that the corner the rules of the Michigan Board of established, monumented, re-rules, all in the same town and accessories and the rules of the Michigan Board of the rules of the R	of 1970, the corner points ment of rules therefore as required it it ment of the Interior, Bureau of the points mentioned in lines 3, 4 of Land Surveyors or by a Decremonumented, recovered, four and range, may be recorded d/or subsequent restoration 21 & 22, T45N-R12W	n the Land 7 and 5 8 19 20 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	3 27 26 25 3 34 35 36 36 3 34 35 36 36 36 36 36 36 36 36 36 36 36 36 36

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

Corner perpetuated as part of the Luce County Remonumentation Program.

Found two corners in the area. Found a 1/2" iron with a wood post next to it. Falls on extension of centerline gravel roads to South and East. Found a bent 2" O.D. pipe set in concrete N57°E, 10.4' from the 1/2" iron. A fence line 1/2 mile East (South side of road) is an even split in distance between the 1/2" iron and the Northeast corner of Section 22. Remains of a fence line 1/2 mile South (East side of road) is an even split in distance between the 1/2" iron and the Southwest corner of Section 22. Accepted found 1/2" iron as corner position. Replaced existing iron with a 1/2" x 48" iron with a 3 1/4" diameter stamped aluminum cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 1/2" x 48" iron with a 3 1/4" diameter stamped aluminum cap, 2" above ground. Falls on extension of centerline of County Road 436 to the South and East (road curves, gravel). Field Line/Tree Line to the West.

Power Pole NY3/169/15 N76°E 132.27' S12°E 24" Maple 119.94' 7" Maple of Twin N71°W 33.94' 8" White Birch NO4°E 2.59'

KARR LAND UR VEYOR

27450 Surveyor's Michigan License No. _

Signed by

MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 LTICES REVISED MAY 14, 1975 NOTE: Bearings are compass bearings corrected for declination. Distances

are to a nail with P.S. 27450 tag in side of witness objects unless noted.

REVISED JAN., 1983