COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Fo	or corners in	Filing Require	ment of Act 74, Mi	ch. P.A. 1970			
	Luce	Located In:	Corner Code ##	1			
_	(County)	Located III.	Corner Code	Filed	1/2-22 A.D.		
1.	Public Land Survey	т <u>45N</u> _R <u>12W</u> т	K-7	At.	10:00 o'clock	A.M.	
		T R		_ File	No. page	528	
2.	Property Controlling	T R S T R			athy S.7	Valar	
in Section S T R					ce County Reg. o	Deeds	
3.	Miscellaneous Property in Sec.	S T R S T R		Reg	ister of Deeds Star	np & File Number	
1	Lot No.	loopeded Diet					
Lot No, Recorded Plat Private Claims						F G H I J K L M	
					2 6 5 5	1	
	r 7 ' 3 7 ' Tr	Ct	10	02	4 7 8	3 10 11 12	
i, do	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						
in	in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the						
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5							
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as							
expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded							
	on this certificate.		range, may be reco	Ji ded	12 _3132	34 35 36	
Α	Description of original	monument and accessories and	or subsequent resto	ration:	13		
		ner Sections 13, 14, 23					
Survey recorded in L.1-P.38 of Surveys shows section corner set by Surveyor # 20706 (Corey J. Hughes). 1986: Eino Sainio, L.S. 7873 Survey recorded in L.1-P.92 of Surveys notes corner. Survey does not state what is at corner. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Corner perpetuated as part of the Luce County Remonumentation Program. Found a 1/2" iron with remains of L.S. cap. Falls in intersecting road centerlines. Corner position checks with a found corner from the survey recorded in L.1-P.92 of							
surveys. Accepted corner position as found. Replaced existing iron with a 1/2" x 24" iron with a 3 1/4" diameter stamped aluminum cap. Set a monument box prior to County Road 413 being repaved.							
Corner is a 1/2" x 24" iron with a 3 1/4" diameter stamped aluminum cap, in a monument box. Falls in intersecting road centerlines of County Road 413 (North-South, paved) and County Road 436 (East-West, gravel).							
	4" Spruce 8" Yellow Birch Wood Corner Fence "V" Notch in Nort Anchor Pole 23	e Post h End of 15" C.M.P.	N38°E S60°E S45°W N71°W N46°W	58.70' 77.31' 48.61' 66.34' 49.84'	**************************************	WILLIAM L. KARR LAND SURVEYOR No. 27450	
Sig	gned by Will	- d. K.	Da	to 12/16	43	ERED LAND SURVEY	

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination. Distances

REVISED MAY 14, 1975

are to a nail with P.S. 27450 tag in side of witness objects unless noted.