SURVEY & REMONUMENTATION

APR 2 8 1995

LUCE COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

For corners COMMISSI	ON Filing Requir	ement of Act 74, Mich. P.	A. 1970
Luce (County)	Located In:	Corner Code	Filed 1/20 AD., 19 95
Public Land Survey	T4 <u>5N</u> R <u>11W</u> T4 <u>5N</u> R <u>12W</u> T R	A-5 Same M-5 Corner	File No. page 589 Sathy A. Mahan
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R S T R R S T R R S T R R S T R R S T R R S T R R S T R R S T R R S T R R R S T R R R S T R R R S T R R R S T R R R S T R R R S T R R R R		Luce County Reg. of Deeds Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H I J K L
do hereby certify that under recin lines 1 and 2 above were in current manual of survey instruManagement or by a decree of above were in conformance will Court of Law; established, rexpressed below: NOTE: Not more than 4 con this certificate. A. Description of original (A-5) Section Corr 1841: J. Burd	t set post 8" Beech 16" Beech	of 1970, the corner points mention of rules therefore as required interest of the Interior, Bureau of the points mentioned in lines 3, 4 and Land Surveyors or by a Decremonumented, recovered, found range, may be recorded door subsequent restoration 1, 11 W. and 12 & 13, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	n the Land 7 and 5 8 19 26 21 22 23 24 e of a e of a e of a 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 11
B. Description of corner e (A-5) This corner program. Found a together in road set by Granger su found large blaze Distances to cor Removed spike and	vidence found and/or method er is being re-establ severely bent 3/4" bo intersection. This po rvey and also works we d Beech and Maple fact	applied in restoring or reest ished as part of the olt, 10" spike and a osition works well we ell with witness pipe ing the corner but of work well. Accept th a 1/2" iron and a	he Luce County Remonumentation 1/4" x 2" iron bar all ith distance to R.O.W. corner e to the Northeast. Also ould find no record of them. ted corner position as found.
		,	costing the position of the corner.
(A-5) Corner is a cap and fal centerline	1/2"x 24" iron with a	aluminum "Luce Count Line of a road to the nd on centerline of 1) Added nail) 5041	e West and 1' South of

27450 Surveyor's Michigan License No. 2/450

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless noted.

8/450

REVISED MAY 14, 1975

REVISED MAY 14, 1975