## LUCE COUNTY REMONUMENTATION CORNER

## LAND CORNER RECORDATION CERTIFICATE

_	Filing	Requirement of Act 74			N.	
For corners in			1	LUCE COUNTY		-
Luce (County)	Located In:	Corner Code #		REGISTER OF Recorded	DEEDS	
1. Public Land Survey	T <u>46N</u> R <u>9</u> T R_ T R_	<u>B-9</u>		02-29-1996 1 10-2 / Kathy S. Mar	Page 65	55 
Property Controlling     in Section     Miscellaneous     Property in Sec	S T R S T R S T R S T R		0	REGISTER OF		
Property in Sec.	S IK_	<u> </u>		Register of D	eeds Stamp &	File Number
4. Lot No, Reco	rded Plat		· · · · · · · · · · · · · · · · · · ·	A B C D	E F G H	I J K L M
			<del></del>	2 6 5 -	-43-	1-21
Keith R. Waters I, requirements of P.A. 74, Michiga	, in a field survey on _	08/31, 19 95 do here	by state that under	4 7 0	9-10-	11-12
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed by	d rules therefore as required Interior, Bureau of Land Ma fin lines 3, 4 and 5 above v y a Decree of a Court of	d in the current manual of survey anagement or by a decree of a C vere in conformance with the ru	y instructions of the court of Law and /or les of the Michigan	5 6 —18 —17— 7 8 —19—20—	21 22	-1413
NOTE: Not more than 2 cort on this certificate.	ners, all in the same towr	and range, may be recorded	d	9 30 29	28 27-	26 -25-
		•		11 32 32	33 34	35 36-
				13		
A. Description of original models and B-9 1/4 Corner Common to 1850 - Original ties to set po	Sections 19 & 30, Tov	wn 46 North, Range 9 Wes	<u>st</u>			
		fence to south. Buried 1'				
						-
	÷		•			
B. Description of corner evi	idence found and/or me	ethod applied in restoring or	reestablishing corn	er:		
This corner is being re-estable Found a 1" I.D. iron pipe 19 as called for in 1975 LCRC. witness corner to the Section Re-established 1/4 corner by Section corner C-9. Corner is 33 feet north of the north of	.3 feet south of the cer It appears that the 1" corner C-9, which was single proportionate refalls 7.04 feet north of	aterline of east-west asphal pipe was mistakenly place is 13.0 feet south of the Se- measurement on line betwee the found 1" pipe. Corner	t road (County Ro d on the line betweetion corner location en Section corner is on the extension	een the Section co on. A-9 and the corre n of a fence line t	orner A-9 and a ct position of the south, and	
·				,		2/8/95 [well]
C. Description of monument	t for corner and accesso	ories established to perpetua	ate locating the pos	ition of the corner:		
Corner is a 1/2" rebar with a on east-west road. (County 16" White Pine, N26°W 41. Power Pole (W&L), S16°E 2	Road 462), on the exte				asphalt paverio	OF MICHIGAN
Power Pole (on west side of Twin 6" Cedar, N05°E 60.92	gravel drive to north),	N33°W 98.89'			H * .	EITH R. VATERS
l" Iron Pipe, SOUTH 7.04' Note: Distances are to a nai.			Trees are blazed	and painted.	<b>*</b>	LAND URVEYOR No.
V H O			Data (7 -	-29-95	Word.	MAND SURVEY
Signed by Keith R Surveyor's Michigan License	No. 33142		_ Date	~ , ,~	The state of the s	THE PARTY OF THE P