Caura	E. Carrier M.
REMONUM	ENTATION .

MAY 28 1997

LUCE COUNTY REMONUMENTATION CORNER

On this certificate. 10 30 29 28 27 26 25 25 26 21 11 30 30 30 30 30 30 30 30 30 30 30 30 30	COMMISSION	LAND	O CORNER RECORDATION	CERTIFICAT	ΓE		
Located In: Corner Code # 1. Public Land Survey 1. Public Land Su	For corners in	Filler	ig Requirement of Act 74, M	lich. P.A. 1970) Luce county		
1. Public Land Survey T46N R 10W T77R R	Luce			1		E EDS	
1. Public Land Survey T45N R 10W G13 Control TR T77N R 10W G13 Control TR TR TR TR TR TR TR TR TR T	(County)	Located In:	Corner Code #		Recorded	p. 70	9
2. Property Controlling S T R R S T R S S T R R S T R S T R S T R S T R S T R S T R R S T		T <u>47N</u> R TR	10W G-13 Corner		Dathy Katha s. Mana	A. Mak r, Register	ar
4. Lot No	in Section 3. Miscellaneous					,	Number
Keith R. Waters in a field survey on 12/10 1996 do hereby state that under the contemporary of the corner points assemblened in lines 1 and 2 above were in conformance with the corner points assemblened in lines 1 and 2 above were in United States Department of the Interior, Bureau of Land Management manual of survey instructions of the Michigan P.A. of 1970, the corner points assemblened in lines 1 and 2 above were in conformance with the corner points assemblened in lines 1 and 2 above were in the Conformance of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, and the corner points assemblened on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restoration: B. Description of comment and accessories and/or subsequent restoration: B. Description of comment at record bearing and distance form soft maple southeast. New witnesses: Preceded Pray's 1964 monument at record bearing and distance form soft maple southeast. New witnesses: Preceded Pray's 1964 monument at record bearing and distance form soft maple southeast. New witnesses: Preceded Pray's 1964 monument at record bearing and distance form soft maple southeast. New witnesses: Preceded Pray's 1964 monument at record bearing and distance form soft maple southeast. New witnesses: Preceded Pray's 1964 monument at record bearing and distance form soft maple southeast. New witnesses: Preceded Pray's 1964 monument at record bearing and distance form soft maple southeast. New witnesses: Preceded Pray's 1964 monument at record bearing and distance form soft maple southeast. New even Pole Support, S40°E 41.45'. B. Description of co	4. Lot No, Recor	ded Plat			·		
in a field survey on 19 of the requirements of P.A. 74 Mehigan P.A. of 1970, the correr points mentioned in fines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the conformance with regulations and rules therefore as required in the current manual of survey instructions of the full rules of the Mehigan poar of Land Surveyers of by a Decree of a Court of Law. established, re-established, monumented, some starting of the conformance with the rules of the Mehigan poar of Land Surveyers of by a Decree of a Court of Law. established, re-established, monumented, some starting of the conformance with the rules of the Mehigan poar of Land Surveyers of by a Decree of a Court of Law. established, re-established, monumented, some starting of the conformance with the rules of the Mehigan poar of Land Surveyers of by a Decree of a Court of Law. established, re-established, monumented, on this certificate. **NOTE:** Note more than 2 corners, all in the same town and range, may be recorded on this certificate. **Description of original monument and accessories and/or subsequent restoration: **Get I.G13. Corner Common to Sections 3 & 4, T40N, R10W & Sections 33 & 34, T47N, R10W. **Bart - Original lies to set post (folim Burit): Birch 12, N10°E 49 links. Birch 12, N15°W 23 links. **Birch 12, N15°W 22 links.** **Birch 12, N15°W 24	5. Private Claims				ABCDE	F G H I J	KL
totated of such experiment of the limitor, Sursau of an and Management or by a decrore of 2 cutoff Lew and 3 in the same town and a country restorations of the that the door man and the state of the McNigan Board of Land Surveyors or by a screen of a Court of Land, restablished, re-established, re-established re-established midway on line between 1/4 corners ½ mile east and west. Witnesses: 5° Soft Maple, SO2°E 64 links - 5° Soft Maple, NO4°E 62 links. 1994 - Steptan J. Szyazkoski, P.S. 33986, liber 2, page 692. Luce County recorded corners. Found and accepted Bray's 1964 monument at re-ord bearing and distance from soft maple southeast. New witnesses: Fence Post, NORTH 40.3° - 5° Soft Maple, SO2°E 42.5° - Power Pole (ML1-167), N40°E 43.2° - Power Pole Support, \$40°E 41.45°. 18. Description of corner evidence found and/or method applied in restoring or reestablishing corner: This corner is being perpetuated as part of the Luce County Romonumentation Program. Found a large spike with plastic cap #33142, 3.5 feet north of centerline. Spike checks well with four found witness objects, as shown in LCRC in liber 2, pa	J ₁	, in a field survey on	10 de hacebu ete	nia iliana auraban		- 4 - 3 - 2	12
A Description of original monument and accessories and/or subsequent restoration: G.1 (G-13) Corner Common to Sections 3 & 4. T46N, R10W & Sections 33 & 14. T47N, R10W 1841 - Original ties to set post (John Burt): Birch 12, N10°E 49 links - Birch 12, N58°W 23 links. 1964 - Frank J. Bray, RLS, page 569A of Luce County recorded corners. Corner re-established midway on line between 1/4 corners ½ mile east and west. Wimesses: 5° Soft Maple, S02°E 64 links - 5° Soft Maple, N04°E 62 links. 1994 - Stephan J. Szyszkoski, P.S. 33986, liber 2, page 629, Luce County recorded corners. Found and accepted Bray's 1964 monument at record bearing and cistance from soft maple southeast. New witnesses: Frence NoRTH 40.3° - 5° Soft Maple, S02°E 42.5° - Power Pole (ML1-167), N40°E 43.2° - Power Pole Support, S40°E 41.45°. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: This corner is being perpetuated as part of the Luce County Remonumentation Program. Found a large spike at surface of asphalt road, 3.5 feet north of centerline. Spike checks well with four found witness objects as shown in LCRC in liber 2, page 629. Accepted corner as found and placed a plastic cap #33142 on spike. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a large spike with plastic cap #33142, 3.5 feet north of the centerline of County Road 407. Witnesses: 5° Soft Maple, S02°E 42.36' Fence Post, NORTH 40.24' Power Pole (ML1-167), N40°E 43.14' Power Pole (ML1-167), N40°E 43.14' Power Pole (ML1-167), N40°E 43.14' Power Pole Support, S40°E 41.45' Date 12–30 –36	United States Department of the i that the corner points mentioned Board of Land Surveyors or by	Intest therefore as require interior, Bureau of Land M. In lines 3, 4 and 5 above to a Decree of a Court of	d in the current manual of survey instru lanagement or by a decree of a Court o were in conformance with the rules of	uctions of the if Law and /or the Michigan nonumented,	6 -18 -17 7	16 25 14 21 22 2:	J 13-13-13-13-13-13-13-13-13-13-13-13-13-1
A Description of original monument and accessories and/or subsequent restoration: GI.(C-13) Corner Common to Sections 3 & 4, T46N, R10W & Sections 33 & 34, T47N, R10W 1841 - Original ties to set post (John Burt): Birch 12, N10°E 49 links - Birch 12, N58°W 23 links. 1964 - Frank J. Bray, RLS, page 569A of Luce County recorded corners. Corner re-established midway on line between 1/4 corners ½ mile east and west. Witnesses: 5" Soft Maple, S02°E 64 links - 5" Soft Maple, N04°E 62 links. 1994 - Stephan J. Szyzakoski, P.S. 33986, liber 2, page 629, Luce County recorded corners. Found and accepted Bray's 1964 monument at record bearing and distance from soft maple southersts. New witnesses: Found and accepted Bray's 1964 monument at record bearing and distance from soft maple southersts. New witnesses: Found and accepted Bray's 1964 monument at record bearing and distance from soft maple southersts. New witnesses: Found and accepted Bray's 1964 monument at record bearing and distance from soft maple southersts. Nor. Nor. H 40.3' - 5" Soft Maple, S02°E 42.5' - Power Pole (ML1-167), N40°E 43.2' - Power Pole Support, S40°E 41.45'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: This corner is being perpetuated as part of the Luce County Remonumentation Program. Found a large spike at surface of asphalt road, 3.5 feet north of centerline. Spike checks well with four found witness object. Bearings are compass bearings are corner and accessories established to perpetuate locating the position of the corner: Corner is a large spike with plastic cap #33142, 3.5 feet north of the centerline of County Road 407. Witnesses: Signed by LAR - Wall H. A. Wall H.	NOTE: Not more than 2 com on this certificate.	ers, all in the same towr	n and range, may be recorded	1	0 30 29	-28 27 26	25
G-1 (G-13) Corner Common to Sections 3 & 4. T46N, R10W & Sections 33 & 34, T47N, R10W 1841 - Original ties to set post (John Burt): Birch 12, N10°E 49 links - Birch 12, N58°W 23 links. 1964 - Frank J. Bray, RLS, page 569A of Luce County recorded corners. Corner re-established midway on line between 1/4 corners ½ mile east and west. Witnesses: 5° Soft Maple, S02°E 64 links - 5° Soft Maple, N04°E 62 links. 1994 - Stephan J. Szyszkoski, PS. 33986, liber 2, page 629, Luce County recorded corners. Formal and accepted Bray's 1964 monument at record bearing and distance from soft maple southeast. New witnesses: Fence Post, NORTH 40.3° - 5° Soft Maple, S02°E 42.5° - Power Pole (ML1-167), N40°E 43.2° - Power Pole Support, S40°E 41.45°. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: This corner is being perpetuated as part of the Luce County Remonumentation Program. Found a large spike at surface of asphalt road, 3.5 feet north of centerline. Spike checks well with four found witness objects as shown in LCRC in liber 2, page 629. Accepted corner as found and placed a plastic cap #33142 on spike. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a large spike with plastic cap #33142, 3.5 feet north of the centerline of County Road 407. Witnesses: S' Soft Maple, S02°E 42.36' Fence Post, NORTH 40.24' Power Pole (ML1-167), N40°E 41.45' Note: Distances are to a nail and washer in the side of the witness object. Bearings are compass bearings corrected for declination. Date 12-30-36				1	2 31 32	33 34 35	3'6
This corner is being perpetuated as part of the Luce County Remonumentation Program. Found a large spike at surface of asphalt road, 3.5 feet north of centerline. Spike checks well with four found witness objects as shown in LCRC in liber 2, page 629. Accepted corner as found and placed a plastic cap #33142 on spike. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a large spike with plastic cap #33142, 3.5 feet north of the centerline of County Road 407. Witnesses: 5" Soft Maple, S02°E 42.36' Fence Post, NORTH 40.24' Power Pole (ML1-167), N40°E 43.14' Power Pole (ML1-167), N40°E 43.14' Power Pole Support, S40°E 41.45' Note: Distances are to a nail and washer in the side of the witness object. Bearings are compass bearings corrected for declination. Date 12-30-96	1964 - Frank J. Bray, RLS, p corners ½ mile east at 1994 - Stephan J. Szyszkosk monument at record b	page 569A of Luce Cond west. Witnesses: 5 ii, P.S. 33986, liber 2, pearing and distance fi	ounty recorded corners. Corner 5" Soft Maple, S02°E 64 links - page 629, Luce County recorde rom soft maple southeast. New	re-established r 5" Soft Maple, d corners. Fou witnesses: Fen	midway on line bet N04°E 62 links. and and accepted B ace Post, NORTH 4	ray's 1964	
Found a large spike at surface of asphalt road, 3.5 feet north of centerline. Spike checks well with four found witness objects as shown in LCRC in liber 2, page 629. Accepted corner as found and placed a plastic cap #33142 on spike. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a large spike with plastic cap #33142, 3.5 feet north of the centerline of County Road 407. Witnesses: 5" Soft Maple, S02°E 42.36' Fence Post, NORTH 40.24' Power Pole Support, S40°E 41.45' Note: Distances are to a nail and washer in the side of the witness object. Bearings are compass bearings corrected for declination. Date 12-30-46	B. Description of corner evid	lence found and/or me	thod applied in restoring or reesta	ablishing corner:			
Corner is a large spike with plastic cap #33142, 3.5 feet north of the centerline of County Road 407. Witnesses: 5" Soft Maple, S02°E 42.36' Fence Post, NORTH 40.24' Power Pole (ML1-167), N40°E 43.14' Power Pole Support, S40°E 41.45' Note: Distances are to a nail and washer in the side of the witness object. Bearings are compass bearings corrected for declination. Date 12-30-96	Found a large spike at surfac	e of asphalt road, 3.5	feet north of centerline. Spike of	checks well with	42 on spike.	CE CO	144 20 M
Corner is a large spike with plastic cap #33142, 3.5 feet north of the centerline of County Road 407. Witnesses: 5" Soft Maple, S02°E 42.36' Fence Post, NORTH 40.24' Power Pole (ML1-167), N40°E 43.14' Power Pole Support, S40°E 41.45' Note: Distances are to a nail and washer in the side of the witness object. Bearings are compass bearings corrected for declination. Date 12-30-96	C. Description of monument f	or corner and accesso	ries established to perpetuate loc	ating the positio	n of the corner	Million in the Control of the Contro	William .
Power Pole (ML1-167), N40°E 43.14' Power Pole Support, S40°E 41.45' Note: Distances are to a nail and washer in the side of the witness object. Bearings are compass bearings corrected for declination. Signed by Keiter R. Watter Date 12-30-96	Corner is a large spike with p Witnesses:	plastic cap #33142, 3.			07.	TE OF MICHIGAN	DAY.
Note: Distances are to a nail and washer in the side of the witness object. Bearings are compass bearings corrected for declination. Signed by Keith R. Watter Date 12-30-96	Power Pole (ML1-167), N40				**	PROFESSIONAL	08 * *
22142					Marie Marie Comment	No. 33142 SIS	
22142	Signed by Kaith Q	(4) n/.	,	Data () === 1	~9L	Commence.	
		221.42		nate 'C 201) · (O		·