## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in Luce	Located In:	Corner Code ##		•	
1. Public Land Survey	T 46N R 10H	F2			
2. Property Controlling	T R T R S4 T46N R10W	4			
in Section 3. Miscellaneous Property in Sec.	S T R S T R S T R		Register of	f Deeds Stamp	& File Number
4. Lot No, Re 5. Private Claims	corded Plat4 Dec 02 F2 Feb 25	1999	2 A	B C D E F	G H   J K L M
do hereby certify that under require lines 1 and 2 above were in a current manual of survey instructions where in contract manual of survey instructions with a contract of Law; established, reexpressed below:	in a field survey on	, 19	tin the fland 7 4 and 5 8 1 ree of a	8 9 9 16 16 16 16 16 16 16 16 16 16 16 16 16	15 14 13 14 13 14 13 14 13 14 13 14 13 14 15 14 15 14 15 16 1
NOTE: Not more than 4 coron this certificate.	rners, all in the same town a	nd range, may be recorde	d 11 12 3	32 33	34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (F2) Center of Section 4. Corner not established in the original survey. Found no subsequent record.

  (4-Sec. 4) Northwest 1/16 corner of Section 4. Corner not established in the original survey. Approximate corner established by MI Dept. of Conservation foresters ca. 1957-1960 who set wooden post at "approximate forty corner". Eino Sainio, PS placed "t"-iron at location of this post in 1984 (survey recorded L2-P28, Luce County Records).
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F2) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/4 corners. At the position for the corner I placed a 1"ID x 36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. I used the 1/4 corner between Sections 4-5 as recorded by Keith Waters, PS, and approved by the Luce Co. Remonumentation Peer Review 12/12/97, to control the E-W 1/4 line in the establishment of this corner.

  (4-Sec. 4) Recovered the "t"-iron placed by Mr. Sainio and the remains of the approximate post. Established the corner at the intersection of straight lines connecting opposite 1/16 corners. The "t"-iron is NO5W (magnetic), 7.3' from this position. At the position for the corner, I placed a 1"IDx36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

(F2) Set 1" pipe with 4" MDNR cap.
Blazed, scribed, and set measuring nails
in the following:
14" R. Pine N80W 27.35' "CS BT"
6" R. Pine S72W 27.25' do
5" W. Birch S17E 13.6' do
6" W.Birch in clump N56E 15.6' "CS BT"
Placed 3" cedar post adjacent. Bearings
are magnetic

(4) Set 1" pipe with 4" MDNR cap.
Blazed, scribed, and set measuring nails
in the following:
24" Maple N54W 30.2' "NW1/16 BT".
18" Maple N24E 26.5' do
4" Cherry East 2.7' do
6" W.Birch S43E 21.1' do
T-iron N5W 7.3'
Placed squared cedar post adjacent.
Bearings are magnetic.



2/22/00

Signed by Stephen

Syfffol.

ate \_\_\_\_\_

Surveyor's Michigan License No.

33986

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971.

REVISED MAY 14, 1975.

REVISED JAN. 1983